

## List of Contributing Structures in the Historic District

Buildings	Common Name	1986 Survey	1991 Survey	2005 Survey (Proposed)
14300 Beacon Avenue	Beacon Auto Parts	√		
14314 Beacon Avenue	Country Cupboard		√	
14315 Beacon Avenue	Touch of Class Pet Grooming	√	√	√
14316 Beacon Avenue	Old Bank Antiques	√	√	√
14320-24 Beacon Avenue	Emporium Antiques		√	√
14329 Beacon Avenue	Residence	√	√	
14330 Beacon Avenue	Anna B's Antiques	√	√	√
14339 Beacon Avenue	Residence	√	√	√
14401 Beacon Avenue	Residence		√	
14403 Beacon Avenue	Residence		√	
14407 Beacon Avenue	Residence	√		
14435 Beacon Avenue		√		
14414 First Avenue	Residence	√		
14420 First Avenue	Residential	√		
14420 Second Avenue	Cox House & Barn	√		√
14438 Second Avenue	Residence	√		
9830 144 <sup>th</sup> Place	John Humphrey House	√	√	√
9833 144 <sup>th</sup> Place	Residence	√		
9852 144 <sup>th</sup> Place	Residence	√		
9853 144 <sup>th</sup> Place	Residence	√		
9856 144 <sup>th</sup> Place	Residence	√		
9883 144 <sup>th</sup> Place	Residence	√		
9909 144 <sup>th</sup> Place	Residence	√		
9933 143 <sup>rd</sup> Place	Residence		√	
14306 Union Avenue	Old Orland Insurance	√	√	√
14314 Union Avenue	General Store Antiques		√	√
14414 Union Avenue		√		
9911-9919 143 <sup>rd</sup> Place	Cracker Barrel Antiques		√	
9911 143 <sup>rd</sup> Place		√		
9825 144 <sup>th</sup> Street		√		
9835 144 <sup>th</sup> Street	Residential		√	
9855 144 <sup>th</sup> Street	Residence	√	√	
9952 144 <sup>th</sup> Street	Residence	√	√	√
9955 144 <sup>th</sup> Street	Orland Methodist Parsonage	√	√	
9967 144 <sup>th</sup> Street	Twin Towers Church	√	√	√
9976 144 <sup>th</sup> Street	Residence		√	
9875 143 <sup>rd</sup> Street	Paddy B's	√	√	
9911 143 <sup>rd</sup> Street	Young's Dry Cleaners	√		
9917 143 <sup>rd</sup> Street	Elia's Day Spa	√	√	√
9925 143 <sup>rd</sup> Street	Threadneedle Street	√	√	√
9953 143 <sup>rd</sup> Street	Grider Dental	√	√	√
9960 143 <sup>rd</sup> Street	Park School & Gymnasium	√		√
9975 143 <sup>rd</sup> Street	Church Parsonage (demolished)	√		
9999 143 <sup>rd</sup> Street (West Avenue S. of 143 <sup>rd</sup> Street)	Former Church School	√	√	
9999 143 <sup>rd</sup> Street	Real Estate Ambassadors (former Christ Lutheran Church)	√	√	√
<b>Total # of Properties</b>		<b>35</b>	<b>27</b>	<b>16</b>

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14300 Beacon Avenue

**Common Name** Beacon Auto Parts

**Historic Name**

**Current Use** Vacant

**Historic Use** Commercial

**Integrity** Medium

**Condition** Fair

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



14300 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Commercial / Storefront

**Number of Stories** 1

**Materials**

**Foundation** Not Visible

**Walls** Brick; Vertical wood siding

**Roof** Built-up Bituminous

**Roof Type** Bow truss

**Window Type & Materials** Wood, fixed divided light with transom; some windows boarded over

**Porch**

**Architectural Details** Stepped false-front facade outlined with brick soldier course

**Alterations** A narrow profile false-mansard roof; the portico and door are not original; there is an addition to the side

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14314 Beacon Avenue

**Common Name** Beacon Ave. Antiques

**Historic Name**

**Current Use** Retail/Residential

**Historic Use**

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14314 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Side Gable

**Number of Stories** 2

**Materials**

**Foundation** Brick; addition is concrete block

**Walls** Vertical board; synthetic siding; synthetic shingles

**Roof** Asphalt shingles

**Roof Type** Side Gable; hipped over porch

**Window Type & Materials** Wood double-hung; aluminum storefronts

**Porch** Side porch, open at the second floor, enclosed at the first floor

**Architectural Details**

**Alterations** Shed roof of wood shingles added over storefront windows; siding altered; gabled side addition; storefronts have been altered

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14315 Beacon Avenue

**Common Name** Touch of Class Pet Grooming

**Historic Name**

**Current Use** Commercial/Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14315 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Folk Victorian

**Number of Stories** 2

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable; hipped roof over porch

**Window Type & Materials** Wood, double-hung with 2/2 verticle lights; metal picture window; Queen Anne window with transom at the side of the house

**Porch** "L" shaped porch with turned wood posts, squared balusters, spindlework porch detailing, wide wood steps and hipped roof

**Architectural Details** Original decorative window hoods and casing with incised design, bullseye corner blocks and stepped wood window hood; same wood detail surrounds the front door; interior brick chimney

**Alterations** Siding altered; some windows replaced

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14316 Beacon Avenue

**Common Name** Old Bank Antiques

**Historic Name** Orland State Bank

**Current Use** Retail/Residential

**Historic Use** Commercial/Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



14316 Beacon\_7.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** 20th Century Commercial / Italianate

**Number of Stories** 2

**Materials**

**Foundation** Parged

**Walls** Brick

**Roof** Built-up bituminous

**Roof Type** Flat

**Window Type & Materials** Wood double-hung 1/1 light; wood fixed; transoms with divided light pattern

**Porch**

**Architectural Details** Limestone sills and lintels; limestone ornament at parapet; corbelled brick at parapet capped with limestone; corbelled chimney detail at side of building; painted cornice at first floor; original wood door frames; historic door to commercial space; original wood windows

**Alterations**

## HISTORY

**Original Construction Date** 1920 per limestone marker

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14320-24 Beacon Avenue

**Common Name**

**Historic Name**

**Current Use** Retail/Residential

**Historic Use** Commercial

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



14320-24 Beacon\_5.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Commercial / Storefront

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Front gable behind a false front parapet; side addition has a cross gable roof

**Window Type & Materials** Wood 1/1 double hung; metal sliding

**Porch** Addition has an open porch at the first floor and an open entry porch at the second floor

**Architectural Details** False front facade; wood door frame and windows

**Alterations** Synthetic siding; first floor windows altered; residential wing at the side

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14329 Beacon Avenue

**Common Name** Digital Photo and Video

**Historic Name**

**Current Use** Commercial

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



14329 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1 1/2

**Materials**

**Foundation** Parged

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Front gable; hipped over porch

**Window Type & Materials** Wood 1/1 double-hung; wood picture window; original windows at the side include small sash with three verticle divided lights

**Porch** Open wood porch with brick piers, wood deck, round columns and hipped roof

**Architectural Details**

**Alterations** First floor window has been altered; interior chimney is new brick

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14330 Beacon Avenue

**Common Name** Anna B's Antiques

**Historic Name**

**Current Use** Retail

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



14330 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Folk Victorian

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; wood shingle

**Roof** Wood shingle

**Roof Type** Front gable with hipped porch

**Window Type & Materials** Wood 1/1 light double-hung windows; Queen Anne windows with colored glass transoms

**Porch** Open wood porch with hipped roof with center gable; turned posts, balusters and spindlework; wood doors; formed concrete block piers

**Architectural Details** Wood clapboard with decorative shingles in gables; gingerbread ornament under front upper gable; side gabled bays on each side

**Alterations** Parged interior chimney

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14339 Beacon Avenue

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14339 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Folk Victorian

**Number of Stories** 1 1/2

**Materials**

**Foundation** Parged; covered with plywood

**Walls** Wood clapboard; wood shingles

**Roof** Asphalt shingles

**Roof Type** Front gable; hipped porch and bays

**Window Type & Materials** Wood, 2/2 light. double hung; wood, 1/1 light double hung; wood 1/1 single hung

**Porch** Wood porch open at door only; turned column, wood steps and deck

**Architectural Details** Wood clapboard siding with decorative wood shingles; side bay with hipped roof; some windows have original wood window trim at the top; front door has original transom window

**Alterations** Decorative shingles under gable installed sometime after 1991, source: 1991 Residential Survey photograph

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14401 Beacon Avenue

**Common Name**

**Historic Name**

**Current Use** Vacant lot

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

Individual No

Old Orland Historic District Non-contributing

**National Register**

Individual No



14401 Beacon\_no house.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style**

**Number of Stories**

**Materials**

Foundation

Walls

Roof

Roof Type

Window Type & Materials

Porch

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor**

**Date**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14403 Beacon Avenue



14403 Beacon.jpg

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gable-Front / Altered

**Number of Stories** 2 1/2

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with hipped porch

**Window Type & Materials** Replacements: 6/6 light, double-hung; 1/1 light double-hung; center fixed window with narrow casements to each side divided by four horizontal muntins

**Porch** Open wood porch with turned posts and tall railing

**Architectural Details** None of the details of the original house remain

**Alterations** Original building was a one-story, front gable house and was documented as such in the 1991 Residential Survey. Since that time, the building has been significantly altered so that it no longer retains the height, scale, materials or architectural details of the original

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14407 Beacon Avenue

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



14407 Beacon\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Craftsman

**Number of Stories** 1 1/2

**Materials**

**Foundation** Brick on concrete

**Walls** Wood clapboard; verticle wood boards at dormer

**Roof** Asphalt shingle

**Roof Type** Hipped

**Window Type & Materials** Wood 3/1 double-hung windows (upper windows have 3 verticle muntins)

**Porch** Enclosed front porch with tall brick piers; concrete steps

**Architectural Details** Wide eaves; side bay; hipped dormer with two hinged, single, wood windows; interior brick chimney; ganged windows at the front are grouped in threes

**Alterations** Front portico addition with gabled roof; porch enclosed

## HISTORY

**Original Construction Date** c1915

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14420 First Avenue



14420 First Ave\_2.jpg

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Fair

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Front gable; hipped porch

**Window Type & Materials** Wood 1/1 light double-hung; 2/2 vertical light double-hung; single hung

**Porch** Wood porch with turned posts, squared spindlework, replaced balusters; porch partially enclosed

**Architectural Details** Front door has original transom window

**Alterations** Synthetic siding; rear addition; steps at the side of the house to upper apartment

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14414 First Avenue

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14414 First Ave\_3.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gable-Front / altered

**Number of Stories** 1

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with multiple side gable additions

**Window Type & Materials** Metal 1/1 light double-hung

**Porch** Porch has been fully enclosed

**Architectural Details**

**Alterations** Synthetic siding; replacement windows; multiple additions at each side of the house; interior chimney

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14438 Second Avenue

**Common Name** Doll House

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14438 Second Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1

**Materials**

**Foundation** Parged

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Wood 1/1 light double-hung

**Porch**

**Architectural Details** Windows and door have simple wood hood ornament; side entrance toward the rear

**Alterations** New front steps; new front door;

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14420 Second Avenue

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Fair

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



14420 Second Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Side Gable

**Number of Stories** 2

**Materials**

**Foundation** Limestone

**Walls** Wood clapboard

**Roof** Asphalt shingles

**Roof Type** Side gable; hipped porch

**Window Type & Materials** Wood 2/2 light double-hung; Queen Anne window with leaded glass transom; Queen Anne storm window with leaded glass transom

**Porch** Open porch removed and one story bay additions were built on both sides of the center door; dentils remain; steps are not original

**Architectural Details** Side gable, center entry house, 2 rooms deep and 2 rooms wide; windows have simple wood hood ornament; dentils at the front porch. Property has an historic barn at the rear

**Alterations** Front porch removed, bay additions occupy the space to each side of center entry, non-original wood steps, wood framing at front door is original; non-original shutters; multiple, early, rear additions

## HISTORY

**Original Construction Date** 1880/ Village of Orland Park **Architect/Builder**

**Associated Events, People, Dates** Believed to be the first house built in Orland Park, source: Village of Orland Park

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9999 143rd Street

**Common Name** Old Methodist Church

**Historic Name** Christ Evangelical Lutheran Church

**Current Use** Commercial

**Historic Use** Religious

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9999 143rd St\_3.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Gothic Revival

**Number of Stories** 1+

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with conical tower

**Window Type & Materials** Original stained glass within the gothic arched window above door; remaining gothic arched windows are replacements with applied muntins

**Porch**

**Architectural Details** Projecting center tower is square with vented openings toward the top and with scrolled brackets under the eaves; Gothic arch window openings; gothic arch window over main entrance door;

**Alterations** Synthetic siding; windows have been replaced; front door has been altered; there is a large addition at the side toward the rear

## HISTORY

**Original Construction Date** 1898 per wall plaque

**Architect/Builder**

**Associated Events, People, Dates** Built in 1898 for the Christ Evangelical Lutheran Church, the last congregation in the church was the Presbyterian Church which purchased the building in 1975

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9999 143rd Street, west of corner

**Common Name** Realty Executives

**Historic Name** Rectory

**Current Use** Commercial

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



9999 143rd St\_rectory.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Hipped

**Number of Stories** 1

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Hipped

**Window Type & Materials** Wood 3/1 light, double-hung windows

**Porch** Open wood front porch with front gabled roof, square posts

**Architectural Details** Brick interior chimney

**Alterations**

## HISTORY

**Original Construction Date** 1903 per church building plaque **Architect/Builder**

**Associated Events, People, Dates** This house served as the rectory to the adjacent church

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9960 143rd Street

**Common Name** Park Avenue School & Gym

**Historic Name** Orland Park School

**Current Use** School

**Historic Use** School

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9960 143rd St\_9.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Prairie with Georgian Revival features

**Number of Stories** 2

**Materials**

**Foundation** Parged

**Walls** Brick

**Roof** Asphalt shingle

**Roof Type** Hipped

**Window Type & Materials** Wood, 4/4 vertically divided light, double-hung windows; some windows have three sash, each with 4 vertically divided lights; smaller 3/3 vertically divided light windows

**Porch**

**Architectural Details** Horizontal emphasis; center raised entrance with pedimented gable; double doors with sidelights, arched transoms and limestone key details in the brick arch; original wall mounted light fixtures; limestone plaque which reads "Orland Park School"; there is a semi-circular, divided light window within the pedimented gable; the ribbon windows have limestone sills

**Alterations** There is a 1940 Joliet limestone gymnasium addition to the west and a steel and glass, International style addition to the east

## HISTORY

**Original Construction Date** 1922 per wall plaque

**Architect/Builder** Architect: Alfred E. Pashley, source: Village of Orland Park

**Associated Events, People, Dates** The 1940 gymnasium addition was designed by an architect by the name of Pomeroy, source: Village of Orland Park

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9975 143rd Street

**Common Name**

**Historic Name**

**Current Use** Parking Lot

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style**

**Number of Stories**

**Materials**

**Foundation**

**Walls**

**Roof**

**Roof Type**

**Window Type & Materials**

**Porch**

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9953 143rd Street

**Common Name**

**Historic Name**

**Current Use** Commercial

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



9953 143rd St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gable-Front with Folk Victorian details

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; wood shingle

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Metal 1/1 light double-hung

**Porch** Wood, open porch with turned posts and balusters; front gable roof with wood shingles in the gable

**Architectural Details** Wood shingles in the gable of the house and of the porch; original window frames remain with squared, decorative window hoods

**Alterations** New front door; replacement windows; new concrete ramp from sidewalk to front door

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9925 143rd Street



9925 143rd St\_4.jpg

**Common Name**

**Historic Name**

**Current Use** Retail

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Italianate

**Number of Stories** 2

**Materials**

**Foundation** Parged

**Walls** Composition shingle

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Wood 2/2 vertically divided light, double-hung windows; Queen Anne window at first floor

**Porch** Open, wood porch with turned posts and squared balusters; hipped roof

**Architectural Details** Arched window hoods at second floor of primary elevation; secondary elevations have pedimented window hoods; transom over front door; wood decorative trim and circular window at the gable

**Alterations** Composition siding; non-original shutters

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9917 143rd Street

**Common Name** Elia's Day Spa / Allstate

**Historic Name**

**Current Use** Commercial

**Historic Use** Commercial

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



9917 143rd St\_3.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Tudor Revival

**Number of Stories** 1

**Materials**

**Foundation** Not Visible

**Walls** Brick

**Roof** Asphalt shingle

**Roof Type** Gable-on-hip

**Window Type & Materials** Wood, fixed picture windows

**Porch**

**Architectural Details** Arched masonry detail around doors including irregular limestone arch stones; irregular facade heights, entrance gables and roof forms; limestone window sills; window transoms covered over

**Alterations** Transoms blocked; new awnings and lighting mounted to the brick facade; doors replaced

## HISTORY

**Original Construction Date** c1935

**Architect/Builder**

**Associated Events, People, Dates** Served as Orland Park's first Public Library, source: Village of Orland Park

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9911 143rd Street

**Common Name** Young's Dry Cleaners

**Historic Name**

**Current Use** Commercial

**Historic Use** Commercial

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



9911 143rd St\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Commercial / Storefront

**Number of Stories** 1

**Materials**

**Foundation** Not Visible

**Walls** Brick

**Roof** Built-up Bituminous

**Roof Type** Bow truss

**Window Type & Materials** Wood, fixed display

**Porch**

**Architectural Details** False storefront facade; tall arched window openings on the sides have been bricked in

**Alterations** Aluminum door, sidelights and transoms are not original; window transoms have been boarded over; windows have limestone sills

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9875 143rd Street

**Common Name** Paddy B's

**Historic Name**

**Current Use** Commercial/Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Fair

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



9875 143rd St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** 20th Century Commercial

**Number of Stories** 2

**Materials**

**Foundation** Not Visible

**Walls** Brick; wood siding

**Roof** Built-up Bituminous

**Roof Type** Flat

**Window Type & Materials** Wood 1/1 light double-hung; aluminum sliding; aluminum 1/1 double-hung

**Porch**

**Architectural Details** Limestone belt course and window sills; limestone decoration at the parapet and limestone coping

**Alterations** Hipped roof over first floor level; windows altered; first floor siding altered; doors altered

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9825 144th Street



9825 144th St\_2.jpg

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Upright-and-Wing

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with side gable ell

**Window Type & Materials** Wood, 1/1 light, double-hung; wood fixed

**Porch** Portico with hipped roof, concrete stair and corner support missing

**Architectural Details**

**Alterations** Synthetic siding; main entrance altered

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9835 144th Street



9835 144th St.jpg

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Fair

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Commercial / Storefront; house: National with cross gable roof

**Number of Stories** 2

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** False front with front gable detail in the center; house addition has a cross gable roof form

**Window Type & Materials** Wood 1/1 light double-hung; metal pivot

**Porch** Enclosed porch with hipped roof

**Architectural Details**

**Alterations** Synthetic siding; windows altered; porch enclosed; doors altered

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9855 144th Street

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



9855 144th St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Upright-and-Wing

**Number of Stories** 2

**Materials**

**Foundation** Parged; wing has formed concrete block

**Walls** Synthetic siding; synthetic shingles in gable

**Roof** Asphalt shingle

**Roof Type** Front gable with side gable wing

**Window Type & Materials** Metal / vinyl replacement 1/1light double-hung; replacement fixed window with transom

**Porch** Front porch enclosed;

**Architectural Details** Pediment detail above windows on front facade; paired windows at second floor; replacement shingles in gable

**Alterations** Synthetic siding; windows have been replaced; synthetic shingle detail; front porch enclosed; front door and entry altered

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9952 144th Street

**Common Name**

**Historic Name** Loebe House

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



9952 144th St\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Queen Anne

**Number of Stories** 2 1/2

**Materials**

**Foundation** Limestone

**Walls** Synthetic siding; wood shingle

**Roof** Asphalt shingle

**Roof Type** Gable-on-hip with conical tower

**Window Type & Materials** Wood, Queen Anne window ; wood 6/1 light and 1/1 light double-hung; small hinged sash with divided lights

**Porch** Newly rebuilt open front portico with square posts, front gabled roof with wood shingles in the gable; concrete steps

**Architectural Details** The front of the house has a bay with shed roof and open porch to the side; one side of the house has a tower bay which retains the wood decorative siding; the other side of the house has a bay with clipped corners; window hoods have been panned with synthetic siding

**Alterations** Synthetic siding; rear addition; side screened porch addition toward the rear; porch altered;

## HISTORY

**Original Construction Date** 1898 per owner

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9955 144th Street

**Common Name** Twin Towers Parsonage

**Historic Name** United Methodist Church  
Parsonage

**Current Use** Vacant

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9955 144th St\_parsonage.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Craftsman, altered

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; asphalt shingles on dormer walls

**Roof** Asphalt shingle

**Roof Type** Hipped with hipped dormer

**Window Type & Materials** Wood 1/1 light, double-hung; fixed leaded glass

**Porch** Open, integral, wood porch with square columns and replacement balustrade

**Architectural Details** Ribbon windows at first floor at the porch; open eaves; hipped roof dormers with ribbon of three small windows and exposed rafter tails; squared side bay

**Alterations** Replacement front porch railing; rafters exposed only on one side; siding on dormer has been altered

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9967 144th Street

**Common Name** United Methodist Church

**Historic Name** Twin Towers Church

**Current Use** Social / Religious

**Historic Use** Religious

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** Yes



9967 144th St\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Queen Anne

**Number of Stories** 1+ towers

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; wood decorative shingles

**Roof** Asphalt shingle

**Roof Type** Front gable with conical, bell shaped towers

**Window Type & Materials** Wood 1/1 light double-hung pointed arch; wood 1/1 light double-hung round arch; opaque glass (opaque glass installed in 1940 which replaced clear glass)

**Porch**

**Architectural Details** Wood clapboard, diamond and fishscale shingles; carved brackets under wide eaves; pointed and round arched windows; circular window under front gable; two octagonal towers

**Alterations** Foundation raised (1918), stone foundation replaced with concrete block raised foundation; center entry constructed in 1942 and removed sometime after 1991; large sanctuary addition to the west (1961); raised east entry added sometime after 1991

## HISTORY

**Original Construction Date** 1898 per plaque

**Architect/Builder** Architect: William Arthur Bennett

**Associated Events, People, Dates** Listed on the National Register of Historic Places; significant dates for the building: 1898 & 1918. Interior has a Sullivanesque pressed metal ceiling

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9976 144th Street

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9976 144th St\_3.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Upright-and-Wing

**Number of Stories** 2

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with side gable wing

**Window Type & Materials** 1/1 replacement windows; 6/6 replacement windows with applied muntins

**Porch** Integral porch under side gabled roof of the side wing; screened with turned posts and balusters

**Architectural Details** Paired window at first floor; squared window hoods; gabled roof dormers

**Alterations** Synthetic siding; windows have been replaced; gabled roof dormers have been added since 1991; porch enclosed

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14306-14310 Union Avenue

**Common Name** Old Orland Insurance

**Historic Name** Orland Park Hotel

**Current Use** Commercial/Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14306-10 Union Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Commercial / Storefront / Italianate

**Number of Stories** 2+

**Materials**

**Foundation** Brick

**Walls** Wood clapboard; synthetic

**Roof** Asphalt shingles

**Roof Type** Front gable with false facade front

**Window Type & Materials** Wood 1/1 double-hung; wood 2/2 vertical light double-hung; storefronts: fixed divided lights

**Porch**

**Architectural Details** False facade front with Italianate details; cornice has paired, carved brackets and dentils under the eave; segmental arch window hoods at front and squared window hoods at sides; cornice above first floor has carved brackets and dentils under the eave; uppermost center window opening has paired arched topped windows

**Alterations** Synthetic siding; storefronts have been altered; doors altered; transom over door covered

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14314 Union Avenue

**Common Name** Union Avenue General Store

**Historic Name**

**Current Use** Commercial/Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14314 Union Ave\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Commercial / Storefront / Italianate

**Number of Stories** 2

**Materials**

**Foundation** Limestone; parged; brick at additions

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with squared false facade front; residential additions are side gable with hipped porch roofs

**Window Type & Materials** Wood fixed windows at storefronts with original bulkheads and paired wood doors and transoms; wood 1/1 double-hung windows; residential addition has Queen Anne window

**Porch** Open porch with turned wood posts and hipped roof

**Architectural Details**

**Alterations** Synthetic siding; window hoods have been removed; early residential addition

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9911 143rd Place

**Common Name** Cracker Barrel Antiques

**Historic Name**

**Current Use** Commercial

**Historic Use** Commercial

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9911 143rd Place\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Commercial / Storefront

**Number of Stories** 2

**Materials**

**Foundation** Parged limestone; formed concrete block at addition

**Walls** Synthetic siding

**Roof** Built-up bituminous

**Roof Type** Flat

**Window Type & Materials** Glass block; wood fixed; wood 1/1 double-hung

**Porch**

**Architectural Details**

**Alterations** Front entry altered; siding altered; storefront windows altered; side addition;

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9933 143rd Place

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9933 143rd Place.jpg

## DESCRIPTION

### **Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 2

### **Materials**

**Foundation** Parged limestone

**Walls** Composition shingle

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Wood 1/1 light double-hung; wood paired casements

**Porch** Portico with front gabled roof, concrete steps, metal railings, support posts altered

### **Architectural Details**

**Alterations** Synthetic siding; portico altered; front door altered; synthetic shutters added

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9830 144th Place

**Common Name** Humphrey House

**Historic Name** Humphrey House

**Current Use** Museum

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** Yes



9830 144th Place\_Humphrey House.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Four-over-four, T-form

**Number of Stories** 2

**Materials**

**Foundation** Limestone; brick; formed concrete block; Lannon stone under front porch

**Walls** Wood clapboard

**Roof** Wood shingle

**Roof Type** Side gable; hipped porch

**Window Type & Materials** Wood 6/6 divided light, double-hung

**Porch** Open porch with concrete deck and steps, wood posts

**Architectural Details** Center entry with original French doors with transoms above; wood hood molds over the windows; corbelled brick chimneys visible above the roofline; original wood shutters

**Alterations** Front porch currently undergoing restoration; foundation, concrete deck and steps are replacements

## HISTORY

**Original Construction Date** 1881

**Architect/Builder**

**Associated Events, People, Dates** Home of Senator John Humphrey who was also Orland Park's first mayor serving from 1892-1914; listed on the National Register of Historic Places

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9833 144th Place

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



9833 144th Place\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gabled Ell

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Synthetic siding; wood shingles in gable

**Roof** Asphalt shingle

**Roof Type** Front gable with side gable ell

**Window Type & Materials** Synthetic, replacement 1/1 double-hung

**Porch** Open porch under renovation

**Architectural Details** Wood shingles under front gable; windows at front of house are paired at both first and second floors; side gable ell has side gable, one story bay; interior brick chimney

**Alterations** The gable defining the porch is an alteration; original probably had a shed roof; the siding has been altered; windows have been altered; new front door; octagonal window added under the front gable

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9852 144th Place



9852 144th Place.jpg

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Folk Victorian

**Number of Stories** 1

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Gable-on-hip with side gable additions and hipped bay roofs

**Window Type & Materials** Wood 1/1 light, double-hung, some with arched tops

**Porch**

**Architectural Details** Multiple bays; recessed panel decoration over bay windows; wood, squared hood ornament over windows; side screened porch with gabled roof dormers above

**Alterations** Rear additions; the location of the front entrance has been changed

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9853 144th Place

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9853 144th Place\_2.jpg

## DESCRIPTION

### **Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Hipped

**Number of Stories** 1

### **Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; wood shingle

**Roof** Asphalt shingle

**Roof Type** Hipped with hipped roof dormer

**Window Type & Materials** Wood 1/1 double-hung; a pair of wood hinged windows with 6 divided lights

**Porch** Integral screened porch with historic wood screened door

**Architectural Details** Wide fascia with wood shingles; wide eaves; hipped roof dormer; interior brick chimney

**Alterations** Replacement front door

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9856 144th Place

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9856 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1 1/2

**Materials**

**Foundation** Parged

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Wood 3/1 light double-hung; upper window under gable is 4/4 light double-hung

**Porch** Enclosed front porch with hipped roof and ribbon of three windows on each side of center entry

**Architectural Details** Squared wood, window hood molds over some of the windows; ribbon of three windows on each side of center entry; single center window under front gable

**Alterations** Front door altered

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9883 144th Place



9883 144th Place.jpg

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gable-Front - altered

**Number of Stories** 2

**Materials**

**Foundation** Not visible: Lannon stone synthetic sheet and plywood cover the foundation

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable; hipped porch

**Window Type & Materials** Wood 1/1 double-hung, fixed with transom; synthetic 1/1 double-hung replacements

**Porch** Open "L" -shaped porch with turned wood posts and balusters; hipped roof

**Architectural Details**

**Alterations** Gable-Front house altered with Victorian style porch and large gabled rear addition; synthetic siding; replacement windows

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9909 144th Place

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9909 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Upright-and-Wing altered to Gabled Ell with Folk Victorian details

**Number of Stories** 1 1/2

**Materials**

**Foundation** Limestone

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Front gable with side gable ell and additions

**Window Type & Materials** Wood 1/1 light, double-hung

**Porch** Open, wood "L" shaped with turned wood posts and squared balusters; hipped roof

**Architectural Details** Paired windows in front gable; squared wood hood molds over windows; shingles in gables

**Alterations** Side ell was originally a smaller 1 1/2 story wing, since enlarged; Victorian porch is also a later addition; large rear addition; west elevation has windows openings altered, new, large gabled roof dormers. These alterations made after 1984 survey.

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** Humphrey Woods

**Common Name** Humphrey Woods

**Historic Name** Humphrey Woods

**Current Use** Natural wooded landscape

**Historic Use** Woods

**Integrity** High

**Condition**

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing District

**National Register**

**Individual** No



Humphrey Woods.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style**

**Number of Stories**

**Materials**

**Foundation**

**Walls**

**Roof**

**Roof Type**

**Window Type & Materials**

**Porch**

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005