


VILLAGE OF ORLAND PARK | CENTENNIAL WEST CONCERT VENUE

DESIGN PRESENTATION | 03/07/2023





SITE PLAN












STAGE FLOOR PLAN



ELEVATIONS



SOUTH ELEVATION



NORTH ELEVATION





FRONT VIEW - EXTERIOR MATERIALS




1 SIMULATED WOOD

RESYSTA - PALE GOLDEN (WWW.RESYSTAUSA.COM)



2 RAINSCREEN (FIBER CEMENT PANELS)

EQUITONE LINEA LT20 (WWW.EQUITONE.COM)




3 CONCRETE BASE

SANDBLASTED CONCRETE WITH VERTICAL SCORING





REAR VIEW - EXTERIOR MATERIALS



SIMULATED WOOD

RESYSTA - PALE GOLDEN (WWW.RESYSTAUSA.COM)



MASONRY WALL

ECHELON SPLIT FACE CMU - CHARCOAL SHEFFIELD (HTTPS://WWW.ECHELONMASONRY.COM)



CONCRETE BASE

SANDBLASTED CONCRETE WITH VERTICAL SCORING







IMAGE OF SELECT MATERIALS







LAWN VIEW







LAWN VIEW







VIP VIEW





