

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9911 143rd Place

**Map Key** A- 1

**Common Name** Cracker Barrel Antiques

**Historic Name** Kruspe's Saloon

**Current Use** Commercial

**Historic Use** Commercial

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9911 143rd Place\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** 19th Century Commercial / Storefront

**Number of Stories** 2

**Materials**

**Foundation** Parged limestone; formed concrete block at addition

**Walls** Synthetic siding

**Roof** Built-up bituminous

**Roof Type** Flat

**Window Type & Materials** Glass block; wood fixed; wood 1/1 double-hung

**Porch**

**Architectural Details**

**Alterations** Front entry altered; siding altered; storefront windows altered

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates** Two-story portion was Kruspe's Saloon; one-story wing was a dance hall, drug store, and gym.

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9924-26 143rd Place

**Map Key** A- 2

**Common Name** Optometrist: Dr. J. Sanderson

**Historic Name**

**Current Use** Commercial/Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9924-26 143rd Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** 19th Century Commercial / Storefront, altered

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Synthetic siding, vertical wood siding; jumbo glazed brick (at sides)

**Roof** Built-up bituminous

**Roof Type** Flat; false-front with arched top

**Window Type & Materials** Wood-framed plate glass; synthetic 6/6 with simulated divided lights

**Porch**

**Architectural Details**

**Alterations** Side addition to the west; original recessed entry has been enclosed by the existing facade.

## HISTORY

**Original Construction Date** 1916

**Architect/Builder**

**Associated Events, People, Dates** In "The Orland Story" this building is identified as being constructed by James Creer as a Grocery and Meat Market

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9931 143rd Place

**Map Key** A- 3

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9931 143rd Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Synthetic shingle

**Roof Type** Gable

**Window Type & Materials** 1/1 replacement windows; fixed picture window (not original)

**Porch** Front portico with hipped roof, non-original post and railing

**Architectural Details** Wood trim at eaves, unique 2-story front bay

**Alterations** Siding, windows replaced

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9932 143rd Place

**Map Key** A- 4

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9932 143rd Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front, altered

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Non-original, synthetic windows with simulated divided lights. 4/1 lights and multi-light transom windows with simulated divided lights.

**Porch** Open stair, wood, non-original

**Architectural Details**

**Alterations** This house was substantially reconstructed after a fire; new siding, windows, dormers, bays, front door, & open front stair.

## HISTORY

**Original Construction Date** c1920, reconstructed 2005

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9933 143rd Place

**Map Key** A- 5

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9933 143rd Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 2

**Materials**

**Foundation** Parged limestone

**Walls** Composition shingle

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Wood 1/1 light double-hung; wood paired casements

**Porch** Portico with front gabled roof, concrete steps, metal railings, support posts altered

**Architectural Details**

**Alterations** Synthetic siding; portico altered; front door altered; synthetic shutters added

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9940-52 143rd Place

**Map Key** A- 6

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9940-52 143rd Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoVictorian

**Number of Stories** 2 1/2

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding; smooth cement stucco; wood shingles

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Vinyl: 1/1 and multi-light/1; multi-light transoms

**Porch** Open porches with gabled roofs, square posts and balustrades

**Architectural Details** Simulated half-timbering in the gable ends

**Alterations**

## HISTORY

**Original Construction Date** 1991 - re:permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/12/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9965 143rd Place

**Map Key** A- 7

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9965 143rd Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoColonial

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Side- gable with front gable center bay and dormers

**Window Type & Materials** Vinyl 1/1

**Porch** Shallow gabled roof overhang with no posts; iron railings

**Architectural Details** Two front-facing roof dormers

**Alterations**

## HISTORY

**Original Construction Date** c2000 -re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9966 143rd Place

**Map Key** A- 8

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9966 143rd Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable, with rear wing

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Side- gable

**Window Type & Materials** 1/1 & picture window of vinyl

**Porch** Uncovered stoop with wood railings

**Architectural Details** Rear gabled wing

**Alterations**

## HISTORY

**Original Construction Date** c1945

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/12/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9971 143rd Place

**Map Key** A- 9

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9971 143rd Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** 1/1 wood; casement (non-original)

**Porch** Wood open porch with shallow front gabled roof

**Architectural Details**

**Alterations** Front porch has been altered to increase its depth, and has non-original posts and railings; siding; some windows replaced; rear addition

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9979 143rd Place

**Map Key** A- 10

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9979 143rd Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Folk Victorian, altered

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding & shingles

**Roof** Asphalt shingle

**Roof Type** Gable

**Window Type & Materials** 1/1 vinyl replacement

**Porch** Open front porch with hipped roof, with turned posts and balustrade, wood steps

**Architectural Details** Front bay window; brick chimney with a corbel detail at the top and limestone caps

**Alterations** Non-original front door; non-original siding; windows have been replaced

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9750 143rd Street

**Map Key** B- 1

**Common Name** Nagel's Auto Service

**Historic Name**

**Current Use** Vacant

**Historic Use** Auto Service/Commercial

**Integrity** High

**Condition** Fair

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9750 143rd St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** 20th Century Commercial

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Enameled Panels; Sheet Metal Wall Base

**Roof** Built-up Bituminous

**Roof Type** Flat

**Window Type & Materials** Aluminum framed plate glass; corner window boarded over

**Porch**

**Architectural Details** Eaves of corrugated metal; wood garage doors each with 12 divided lights; aluminum framed glass door

**Alterations**

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9871 143rd Street

**Map Key** B- 2

**Common Name** Hienie's / McCarthy's Catering

**Historic Name**

**Current Use** Retail

**Historic Use** Retail

**Integrity** High

**Condition** Good

### Local Landmark

**Individual** No

**Old Orland Historic District** Non-contributing

### National Register

**Individual** No



9871 143rd St.jpg

## DESCRIPTION

### Inclusion in Previous Surveys

**Architectural Type/Style** 20th Century Commercial

**Number of Stories** 1

### Materials

**Foundation** Concrete

**Walls** Brick (painted)

**Roof** Shingle (on mansard); Built-up Bituminous

**Roof Type** Mansard front; Flat above

**Window Type & Materials** Aluminum- framed plate glass

### Porch

**Architectural Details** Aluminum- framed glass door

**Alterations** Signage has been added at the facade and roof

## HISTORY

**Original Construction Date** c1970

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/12/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9875 143rd Street

**Map Key** B- 3

**Common Name** Paddy B's

**Historic Name**

**Current Use** Commercial/Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Fair

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9875 143rd St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** 20th Century Commercial

**Number of Stories** 2

**Materials**

**Foundation** Not Visible

**Walls** Brick; wood siding

**Roof** Built-up Bituminous

**Roof Type** Flat

**Window Type & Materials** Wood 1/1 light double-hung; aluminum sliding; aluminum 1/1 double-hung

**Porch**

**Architectural Details** Limestone belt course and window sills; limestone decoration at the parapet and limestone coping

**Alterations** Hipped roof over first floor level; windows altered; first floor siding altered; doors altered

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates** The first floor originally had a soda fountain.

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9900 143rd Street

**Map Key** B- 4

**Common Name** Zimmerman & Sandeman Funeral

**Historic Name**

**Current Use** Commercial

**Historic Use** Commercial

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9900 143rd St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoMansard / Commercial

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Stucco, synthetic vertical siding, wood shingles

**Roof** Wood shingle & built-up bituminous

**Roof Type** Deck

**Window Type & Materials** Wood casement

**Porch**

**Architectural Details** Port cochere; large double doors

**Alterations**

## HISTORY

**Original Construction Date** 1981-re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9911 143rd Street

**Map Key** B- 5

**Common Name** Young's Dry Cleaners

**Historic Name**

**Current Use** Commercial

**Historic Use** Commercial

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9911 143rd St\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** 20th Century Commercial / Storefront

**Number of Stories** 1

**Materials**

**Foundation** Not Visible

**Walls** Brick

**Roof** Built-up Bituminous

**Roof Type** Bow truss

**Window Type & Materials** Wood, fixed display

**Porch**

**Architectural Details** False storefront facade; tall arched window openings on the sides have been bricked in

**Alterations** Aluminum door, sidelights and transoms are not original; window transoms have been boarded over; windows have limestone sills

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9917 143rd Street

**Map Key** B- 6

**Common Name** Elia's Day Spa / Allstate

**Historic Name** Orland Park Public Library

**Current Use** Commercial

**Historic Use** Commercial

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9917 143rd St\_3.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Tudor Revival

**Number of Stories** 1

**Materials**

**Foundation** Not Visible

**Walls** Brick

**Roof** Asphalt shingle

**Roof Type** Gable-on-hip

**Window Type & Materials** Wood, fixed picture windows

**Porch**

**Architectural Details** Arched masonry detail around doors including irregular limestone arch stones; irregular facade heights, entrance gables and roof forms; limestone window sills; window transoms covered over

**Alterations** Transoms blocked; new awnings and lighting mounted to the brick facade; doors replaced

## HISTORY

**Original Construction Date** c1916/remodeled c1925

**Architect/Builder** James Pomeroy, architect for the 1925 remodel

**Associated Events, People, Dates** Built by carpenter William Mahaffey for and used by the Loebe Brothers store. It was remodeled by local architect James Pomeroy in the mid-1920s and subsequently served as Orland Park's first Public Library (1937-1974), source: Oral Histories compiled by Joyce Lahti, & also from the Village of Orland Park

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9925 143rd Street

**Map Key** B- 7

**Common Name**

**Historic Name**

**Current Use** Retail

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9925 143rd St\_4.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Italianate

**Number of Stories** 2

**Materials**

**Foundation** Parged

**Walls** Composition shingle

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Wood 2/2 vertically divided light, double-hung windows; Queen Anne window at first floor

**Porch** Open, wood porch with turned posts and squared balusters; hipped roof

**Architectural Details** Arched window hoods at second floor of primary elevation; secondary elevations have pedimented window hoods; transom over front door; wood decorative trim and circular window at the gable

**Alterations** Composition siding; non-original shutters

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9953 143rd Street

**Map Key** B- 8

**Common Name**

**Historic Name**

**Current Use** Commercial

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9953 143rd St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gable-Front with Folk Victorian details

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; wood shingle

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Metal 1/1 light double-hung

**Porch** Wood, open porch with turned posts and balusters; front gable roof with wood shingles in the gable

**Architectural Details** Wood shingles in the gable of the house and of the porch; original window frames remain with squared, decorative window hoods

**Alterations** New front door; replacement windows; new concrete ramp from sidewalk to front door

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9959 143rd Street

**Map Key** B- 9

**Common Name** Nail Sonata

**Historic Name**

**Current Use** Retail/Residential

**Historic Use** Retail/Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9959 143rd St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** 20th Century Commercial with elements of the International style

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Brick, stone

**Roof** Built-up bituminous

**Roof Type** Flat

**Window Type & Materials** Aluminum-framed plate glass storefronts; sliding, fixed & 1/1 synthetic

**Porch**

**Architectural Details** Wood soffit, recessed storefront, stone sills, storefront doors with transom windows

**Alterations**

## HISTORY

**Original Construction Date** c1960

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9960 143rd Street

**Map Key** B- 10

**Common Name** Park Avenue School & Gym

**Historic Name** Orland Park School

**Current Use** School

**Historic Use** School

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9960 143rd St\_9.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Prairie with Georgian Revival features

**Number of Stories** 2

**Materials**

**Foundation** Parged

**Walls** Brick

**Roof** Asphalt shingle

**Roof Type** Hipped

**Window Type & Materials** Wood, 4/4 vertically divided light, double-hung windows; some windows have three sash, each with 4 vertically divided lights; smaller 3/3 vertically divided light windows

**Porch**

**Architectural Details** Horizontal emphasis; center raised entrance with pedimented gable; double doors with sidelights, arched transoms and limestone key details in the brick arch; original wall mounted light fixtures; limestone plaque which reads "Orland Park School"; there is a semi-circular, divided light window within the pedimented gable; the ribbon windows have limestone sills

**Alterations** There is a 1940 Joliet limestone gymnasium addition to the west and a steel and glass, International style addition to the east

## HISTORY

**Original Construction Date** 1922 per wall plaque

**Architect/Builder** Architect: Alfred F. Pashley, source: Village of Orland Park

**Associated Events, People, Dates** The 1940 gymnasium addition was designed by architect James Pomeroy, source: Village of Orland Park

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

## Continuation Sheet

**Address** 9960 143rd Street

**Map Key** B- 10



9960 143rd St\_Addition.jpg



9960 143rd St\_international addition.jpg

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9975 143rd Street

**Map Key** B- 11

**Common Name**

**Historic Name**

**Current Use** Parking Lot

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9975 143rd St\_new.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

2005 Residential Survey; 2005 Residential Survey

**Architectural Type/Style**

**Number of Stories**

**Materials**

**Foundation**

**Walls**

**Roof**

**Roof Type**

**Window Type & Materials**

**Porch**

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9999 143rd Street

**Map Key** B- 12

**Common Name** Old Methodist Church

**Historic Name** Christ Evangelical Lutheran Church

**Current Use** Commercial

**Historic Use** Religious

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9999 143rd St\_3.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Gothic Revival

**Number of Stories** 1+

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with conical tower

**Window Type & Materials** Original stained glass within the gothic arched window above door; remaining gothic arched windows are replacements with applied muntins

**Porch**

**Architectural Details** Projecting center tower is square with vented openings toward the top and with scrolled brackets under the eaves; Gothic arch window openings; gothic arch window over main entrance door;

**Alterations** Synthetic siding; windows have been replaced; front door has been altered; there is a large addition at the side toward the rear

## HISTORY

**Original Construction Date** 1898 per wall plaque

**Architect/Builder**

**Associated Events, People, Dates** Built in 1898 for the Christ Evangelical Lutheran Church, the last congregation in the church was the Presbyterian Church which purchased the building in 1975

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 10001 143rd Street

**Map Key** B- 13

**Common Name** Family Optometry

**Historic Name**

**Current Use** Commercial

**Historic Use** Commercial

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



10001 143rd Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** 20th Century Commercial

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Brick; vertical wood siding

**Roof** Built-up bituminous

**Roof Type** Flat

**Window Type & Materials** Wood: fixed; Metal: 1/1; Aluminum- framed storefront; Glass block

**Porch**

**Architectural Details** Recessed corner entry with aluminum-framed glass door; stone window sills; wide projecting eaves at the roof; vertical wood louver detail demarcating change in floors; awning over storefront windows & door; synthetic siding under eaves

**Alterations**

## HISTORY

**Original Construction Date** c1960

**Architect/Builder**

**Associated Events, People, Dates**



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 10055 143rd Street

**Map Key** B- 14

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



10055 143rd Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick; wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: Chicago windows with fixed center light and 2/2 (horizontal muntins) at each side; 2/2; octagonal; limestone sills

**Porch** Integral porch at secondary entrance in the breezeway

**Architectural Details** Attached two car garage, connected by a slightly recessed and enclosed breezeway; main entrance door is flush with a single square light; secondary entrance adjacent to the garage

**Alterations**

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14327 Highland Avenue

**Map Key** B- 15

**Common Name** St. Michael's Church

**Historic Name**

**Current Use** Religious

**Historic Use** Religious

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



St Michael's Church 143rd Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Contemporary

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick, stone

**Roof** Built-up bituminous

**Roof Type** Flat

**Window Type & Materials** Metal, fixed, art glass

**Porch** Recessed entry at northwest corner with colonnade of three full-height brick columns; recessed and colonnade mirrored at the northeast

**Architectural Details** Limestone cornice band at the roof with carved symbolic panels; tall rectangular art glass windows set in regularly spaced intervals on the facades; multi-story bell tower of open metal at the northwest corner of the church; rear school wing pre-dates construction of the church (1949)

**Alterations**

## HISTORY

**Original Construction Date** 1969

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 10113 143rd Street

**Map Key** B- 16

**Common Name**

**Historic Name**

**Current Use** Vacant Lot

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

Individual

Old Orland Historic  
District

**National Register**

Individual



10113 143rd Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style**

**Number of Stories**

**Materials**

Foundation

Walls

Roof

Roof Type

Window Type & Materials

Porch

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor**

**Date**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 10115 143rd Street

**Map Key** B- 17

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



10115 143rd Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable, altered form

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block; concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable, modified pitch

**Window Type & Materials** Non-original 1/1, fixed and sliding

**Porch** Open concrete steps with metal railings

**Architectural Details** Flush door with large rectangular light in upper part of the door and a Colonial Revival door surround; two front gable roof dormers

**Alterations** Siding, pair of bay windows at the front of the house; original front porch area enclosed and integrated into the house.

## HISTORY

**Original Construction Date** c1915

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 10117 143rd Street

**Map Key** B- 18

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



10117 143rd Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Craftsman

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block; porch foundation not visible

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: 4/1, 3/1 7 single light

**Porch** Retains original integral porch with three sides of windows and paneled porch door with multi-paned divided lights, and sidelights

**Architectural Details** Rafter tails; shed roof dormer; integral porch with original windows

**Alterations** Siding, front deck and steps

## HISTORY

**Original Construction Date** c1915

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 10125 143rd Street

**Map Key** B- 19

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



10125 143rd Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Split Level

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Coursed ashlar limestone and synthetic siding

**Roof** Asphalt shingles

**Roof Type** Cross- gable

**Window Type & Materials** Wood: 1/1 with diamond -pattern applied muntins, some paired

**Porch**

**Architectural Details** Paneled door with large etched glass panel in top half and matching sidelights; attached garage at right angle to the house.

**Alterations**

## HISTORY

**Original Construction Date** 1969- re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9830 144th Place

**Map Key** C- 1

**Common Name** Humphrey House

**Historic Name** Humphrey House

**Current Use** Museum

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

### Local Landmark

**Individual** Yes

**Old Orland Historic District** Contributing

### National Register

**Individual** Yes



9830 144th Place\_Humphrey House.jpg

## DESCRIPTION

### Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Four-over-four, T-form

**Number of Stories** 2

### Materials

**Foundation** Limestone; brick; formed concrete block; Lannon stone under front porch

**Walls** Wood clapboard

**Roof** Wood shingle

**Roof Type** Side gable; hipped porch

**Window Type & Materials** Wood 6/6 divided light, double-hung

**Porch** Open porch with concrete deck and steps, wood posts

**Architectural Details** Center entry with original French doors with transoms above; wood hood molds over the windows; corbelled brick chimneys visible above the roofline; original wood shutters

**Alterations** Front porch currently undergoing restoration; foundation, concrete deck and steps are replacements

## HISTORY

**Original Construction Date** 1881

**Architect/Builder**

**Associated Events, People, Dates** Home of Senator John Humphrey who was also Orland Park's first mayor serving from 1892-1914; listed in the National Register of Historic Places. Donated to the Orland Historical Society in 1987.

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9831 144th Place

**Map Key** C- 2

**Common Name**

**Historic Name**

**Current Use** Vacant Lot

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

Individual

Old Orland Historic  
District

**National Register**

Individual



9831 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style**

**Number of Stories**

**Materials**

Foundation

Walls

Roof

Roof Type

Window Type & Materials

Porch

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9833 144th Place

**Map Key** C- 3

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9833 144th Place\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gabled Ell

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Synthetic siding; wood shingles in gable

**Roof** Asphalt shingle

**Roof Type** Front gable with side gable ell

**Window Type & Materials** Synthetic, replacement 1/1 double-hung

**Porch** Open porch under renovation

**Architectural Details** Wood shingles under front gable; windows at front of house are paired at both first and second floors; side gable ell has side gable, one story bay; interior brick chimney

**Alterations** The gable defining the porch is an alteration; original had a shed roof; the siding has been altered; windows have been altered; new front door; octagonal window added under the front gable

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9851 144th Place

**Map Key** C- 4

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9851 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Minimal Traditional

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding & brick

**Roof** Asphalt shingles

**Roof Type** Hipped & front gable

**Window Type & Materials** 1/1 vinyl; corner ribbon window with two windows that face the front and the third window facing the side, the windows in the brick portion have masonry sills

**Porch** Integral open porch with iron post and concrete steps

**Architectural Details** Large interior brick chimney; glass block sidelight

**Alterations** Siding

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9852 144th Place

**Map Key** C- 5

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9852 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Folk Victorian

**Number of Stories** 1

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Gable-on-hip with side gable additions and hipped bay roofs

**Window Type & Materials** Wood 1/1 light, double-hung, some with arched tops

**Porch**

**Architectural Details** Multiple bays; recessed panel decoration over bay windows; wood, squared hood ornament over windows; side screened porch with gabled roof dormers above

**Alterations** Rear additions; the location of the front entrance has been changed

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9853 144th Place

**Map Key** C- 6

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9853 144th Place\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Bungalow

**Number of Stories** 1

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; wood shingle

**Roof** Asphalt shingle

**Roof Type** Hipped with hipped roof dormer

**Window Type & Materials** Wood 1/1 double-hung; a pair of wood hinged windows with 6 divided lights

**Porch** Integral screened porch with historic wood screened door

**Architectural Details** Wide fascia with wood shingles; wide eaves; hipped roof dormer; interior brick chimney

**Alterations** Replacement front door

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9856 144th Place

**Map Key** C- 7

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9856 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1 1/2

**Materials**

**Foundation** Parged

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Wood 3/1 light double-hung; upper window under gable is 4/4 light double-hung

**Porch** Enclosed front porch with hipped roof and ribbon of three windows on each side of center entry

**Architectural Details** Squared wood, window hood molds over some of the windows; ribbon of three windows on each side of center entry; single center window under front gable

**Alterations** Front door altered

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9860 144th Place

**Map Key** C- 8

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9860 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Brick & wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood 1/1 & Chicago window; masonry sills

**Porch**

**Architectural Details** Wood paneled front door; concrete paver retaining wall; small interior brick chimney; shutters

**Alterations**

## HISTORY

**Original Construction Date** c1940

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9861 144th Place

**Map Key** C- 9

**Common Name**

**Historic Name**

**Current Use** Vacant

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9861 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Contemporary

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick & synthetic siding

**Roof** Asphalt shingle

**Roof Type** Gable

**Window Type & Materials** Wood, Chicago windows; casement at the side

**Porch**

**Architectural Details** Large interior brick chimney with corbel detail at the top; front facade is divided into three bays, each bay separated by brick walls that extend to the roof. There are colored, patterned glass sidelights at the front door.

**Alterations** There is a large two-story gabled addition at the rear of the house (from 2005 re: permit records)

## HISTORY

**Original Construction Date** 1978-re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9867 144th Place

**Map Key** C- 10

**Common Name**

**Historic Name**

**Current Use** Vacant Lot

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

Individual

Old Orland Historic  
District

**National Register**

Individual



9867 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style**

**Number of Stories**

**Materials**

Foundation

Walls

Roof

Roof Type

Window Type & Materials

Porch

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9875 144th Place

**Map Key** C- 11

**Common Name**

**Historic Name**

**Current Use** Vacant Lot

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

Individual

Old Orland Historic  
District

**National Register**

Individual



9875 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style**

**Number of Stories**

**Materials**

Foundation

Walls

Roof

Roof Type

Window Type & Materials

Porch

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9883 144th Place

**Map Key** C- 12

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9883 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gable-Front - altered

**Number of Stories** 2

**Materials**

**Foundation** Not visible: Lannon stone synthetic sheet and plywood cover the foundation

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable; hipped porch

**Window Type & Materials** Wood 1/1 double-hung, fixed with transom; synthetic 1/1 double-hung replacements

**Porch** Open "L" -shaped porch with turned wood posts and balusters; hipped roof

**Architectural Details**

**Alterations** Gable-Front house altered with Victorian style porch and large gabled rear addition; synthetic siding; replacement windows

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9901 144th Place

**Map Key** C- 13

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9901 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Queen Anne

**Number of Stories** 2

**Materials**

**Foundation** Limestone

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped with lower cross gables and conical roof at side tower

**Window Type & Materials** Wood 1/1, multi/1; Queen Anne window

**Porch** Open porch nearly the entire width of the front facade with gabled roof, turned wood posts, balustrade; replacement front door with sidelights

**Architectural Details** Prominent exterior brick chimney with brick decorative detail; corner tower; hipped bay at the side

**Alterations**

## HISTORY

**Original Construction Date** 2003 per owner

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9905 144th Place

**Map Key** C- 14

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9905 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoVictorian - altered from Gable-Front

**Number of Stories** 2

**Materials**

**Foundation** Concrete block; formed concrete block

**Walls** Synthetic siding & shingles

**Roof** Asphalt shingle

**Roof Type** Gable

**Window Type & Materials** Non-original 8/8 & 4/4 with simulated divided lights

**Porch** Non-original, open, L-shaped front porch with entry at rear portion of the porch; turned posts & balustrade

**Architectural Details**

**Alterations** Siding, windows, rear addition higher and wider than original house with gable roof and clipped corner; altered front bay window at the porch; non-original front porch

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9909 144th Place

**Map Key** C- 15

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9909 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gabled Ell with Folk Victorian details, altered from Upright-and-Wing

**Number of Stories** 1 1/2

**Materials**

**Foundation** Limestone

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Front gable with side gable ell and additions

**Window Type & Materials** Wood 1/1 light, double-hung

**Porch** Open, wood "L" shaped with turned wood posts and squared balusters; hipped roof

**Architectural Details** Paired windows in front gable; squared wood hood molds over windows; shingles in gables

**Alterations** Side ell was originally a smaller 1 1/2 story wing, since enlarged; Victorian porch is also a later addition; large rear addition; west elevation has windows openings altered, new, large gabled roof dormers. These alterations made after 1984 survey.

## HISTORY

**Original Construction Date** 1893 per owner

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9915 144th Place

**Map Key** C- 16

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9915 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front, with Folk Victorian elements

**Number of Stories** 1 1/2

**Materials**

**Foundation** Parged

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Non-original 1/1

**Porch** Open, full width with Queen Anne ornament and beadboard ceiling

**Architectural Details** Interior brick chimney

**Alterations** Siding, windows, gabled side addition with concrete block foundation; concrete retaining wall

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9916 144th Place

**Map Key** C- 17

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9916 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch with NeoMediterranean details

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Wood casements

**Porch**

**Architectural Details** Arched window openings; double doors with sunburst storm door; decorative wall sconces; integral garage; interior brick chimney

**Alterations**

## HISTORY

**Original Construction Date** c1970

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9920 144th Place

**Map Key** C- 18

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9920 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 2

**Materials**

**Foundation** Brick, parged

**Walls** Vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood 6/6, vinyl 1/1

**Porch** Enclosed front porch addition with shed roof

**Architectural Details**

**Alterations** Glazed enclosure at second floor with pent roof; the enclosure is very shallow and only wraps around the two windows; front porch addition

## HISTORY

**Original Construction Date** c1890 per Orland Park's HPRC

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9923 144th Place

**Map Key** C- 19

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9923 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable

**Number of Stories** 1

**Materials**

**Foundation** Not visible

**Walls** Wood vertical board and horizontal siding

**Roof** Asphalt shingle

**Roof Type** Gable

**Window Type & Materials** 3/1 wood; 1/1 replacements

**Porch** Enclosed integral porch with seven windows across the front

**Architectural Details** Brick chimney

**Alterations** Siding, windows, non-original door

## HISTORY

**Original Construction Date** c1915

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9927 144th Place

**Map Key** C- 20

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9927 144th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1

**Materials**

**Foundation** Limestone & CMU

**Walls** Wood siding

**Roof** Asphalt shingles

**Roof Type** Gable with hipped additions

**Window Type & Materials** Wood 4/4; Vinyl 1/1, casements with simulated divided lights; non-original bay window

**Porch** Open porch with hipped roof supported by a post and side braces

**Architectural Details** Interior brick chimney; the surrounding site is heavily obstructed making observation difficult.

**Alterations** Hipped wing addition with integral garage; garage addition with flat roof and deck on top; bay window addition

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9825 144th Street

**Map Key** D- 1

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9825 144th St\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Upright-and-Wing

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with side gable ell

**Window Type & Materials** Wood, 1/1 light, double-hung; wood fixed

**Porch** Portico with hipped roof, concrete stair and corner support missing

**Architectural Details**

**Alterations** Synthetic siding; main entrance altered

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9835 144th Street

**Map Key** D- 2

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Fair

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9835 144th St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** 19th Century Commercial / Storefront; house: National with cross gable roof

**Number of Stories** 2

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** False front with front gable detail in the center; house addition has a cross gable roof form

**Window Type & Materials** Wood 1/1 light double-hung; metal pivot

**Porch** Enclosed porch with hipped roof

**Architectural Details**

**Alterations** Synthetic siding; windows altered; porch enclosed; doors altered

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9855 144th Street

**Map Key** D- 3

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9855 144th St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Upright-and-Wing

**Number of Stories** 2

**Materials**

**Foundation** Parged; wing has formed concrete block

**Walls** Synthetic siding; synthetic shingles in gable

**Roof** Asphalt shingle

**Roof Type** Front gable with side gable wing

**Window Type & Materials** Metal / vinyl replacement 1/1light double-hung; replacement fixed window with transom

**Porch** Front porch enclosed;

**Architectural Details** Pediment detail above windows on front facade; paired windows at second floor; replacement shingles in gable

**Alterations** Synthetic siding; windows have been replaced; synthetic shingle detail; front porch enclosed; front door and entry altered

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9860 144th Street

**Map Key** D- 4

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9860 144th St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block, parged

**Walls** Synthetic siding with synthetic shingles in the gable

**Roof** Asphalt shinges

**Roof Type** Gable

**Window Type & Materials** Front: 2/2 wood under gable (with horizontal muntins) & 1/1 vinyl; Side: Chicago window & 1/1 wood

**Porch** Enclosed porch with front door at the side

**Architectural Details** Interior brick chimney; original side bay

**Alterations** Siding, windows, Chicago window, side bay has been enlarged

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9865 144th Street

**Map Key** D- 5

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9865 144th St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Bungalow

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** 1/1 wood

**Porch** Non-original open porch with awning over the front door

**Architectural Details** Original multi-light front door

**Alterations** Siding, dormer windows have been replaced; front porch has newer steps and deck and has fence pickets as balusters

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9875 144th Street

**Map Key** D- 6

**Common Name**

**Historic Name**

**Current Use** Not Yet Constructed

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

Individual

Old Orland Historic  
District

**National Register**

Individual



9875 144th Street\_not const.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style**

**Number of Stories**

**Materials**

Foundation

Walls

Roof

Roof Type

Window Type & Materials

Porch

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9930 144th Street

**Map Key** D- 7

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9930 144th St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Folk Victorian

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Vinyl, 1/1

**Porch** Open front porch with hipped roof, squared columns & posts

**Architectural Details** Bay in front gable has a hipped roof; brick chimney with limestone caps

**Alterations**

## HISTORY

**Original Construction Date** c2000

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9952 144th Street

**Map Key** D- 8

**Common Name**

**Historic Name** Loebe House

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9952 144th St\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Queen Anne

**Number of Stories** 2 1/2

**Materials**

**Foundation** Limestone

**Walls** Synthetic siding; wood shingle

**Roof** Asphalt shingle

**Roof Type** Gable-on-hip with conical tower

**Window Type & Materials** Wood, Queen Anne window ; wood 6/1 light and 1/1 light double-hung; small hinged sash with divided lights

**Porch** Newly rebuilt open front portico with square posts, front gabled roof with wood shingles in the gable; concrete steps

**Architectural Details** The front of the house has a bay with shed roof and open porch to the side; one side of the house has a tower bay which retains the wood decorative siding; the other side of the house has a bay with clipped corners; window hoods have been panned with synthetic siding

**Alterations** Synthetic siding; rear addition; side screened porch addition toward the rear; porch altered;

## HISTORY

**Original Construction Date** 1898 per owner

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9955 144th Street

**Map Key** D- 9

**Common Name** Twin Towers Parsonage

**Historic Name** United Methodist Church  
Parsonage

**Current Use** Vacant

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

### Local Landmark

**Individual** No

**Old Orland Historic District** Contributing

### National Register

**Individual** No



9955 144th St\_parsonage.jpg

## DESCRIPTION

### Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Craftsman, altered

**Number of Stories** 1 1/2

### Materials

**Foundation** Formed concrete block

**Walls** Wood clapboard; asphalt shingles on dormer walls

**Roof** Asphalt shingle

**Roof Type** Hipped with hipped dormer

**Window Type & Materials** Wood 1/1 light, double-hung; fixed leaded glass

**Porch** Open, integral, wood porch with square columns and replacement balustrade

**Architectural Details** Ribbon windows at first floor at the porch; open eaves; hipped roof dormers with ribbon of three small windows and exposed rafter tails; squared side bay

**Alterations** Replacement front porch railing; rafters exposed only on one side; siding on dormer has been altered

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates** This house was used at one time as the Parsonage for the United Methodist Church.

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9955 144th Street

**Map Key** D- 9

**Common Name** Twin Towers Parsonage

**Historic Name** United Methodist Church  
Parsonage

**Current Use** Demolished

**Historic Use** Residential

**Integrity**

**Condition**

**Local Landmark**

Individual

Old Orland Historic  
District

**National Register**

Individual



9955 144th St\_2.jpg

## DESCRIPTION

### **Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

### **Architectural Type/Style**

**Number of Stories**

### **Materials**

**Foundation**

**Walls**

**Roof**

**Roof Type**

**Window Type & Materials**

**Porch**

### **Architectural Details**

### **Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9964 144th Street

**Map Key** D- 10

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9964 144th St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front, altered

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete & brick

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** 1st floor: 6/6, 1/1, Chicago window; Upper window: 6/6 vinyl with simulated divided lights

**Porch**

**Architectural Details** Wood paneled door; wood fascia and eaves; Queen Anne window at the side bay with a center window with transom above, transom bar detailed with dentils

**Alterations** Non-original siding, windows, and front bay, Colonial Revival door surround

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9967 144th Street

**Map Key** D- 11

**Common Name** United Methodist Church

**Historic Name** Twin Towers Church

**Current Use** Social / Religious

**Historic Use** Religious

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** Yes



9967 144th St\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Queen Anne

**Number of Stories** 1+ towers

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; wood decorative shingles

**Roof** Asphalt shingle

**Roof Type** Front gable with conical, bell shaped towers

**Window Type & Materials** Wood 1/1 light double-hung pointed arch; wood 1/1 light double-hung round arch; opaque glass (opaque glass installed in 1940 which replaced clear glass)

**Porch**

**Architectural Details** Wood clapboard, diamond and fishscale shingles; carved brackets under wide eaves; pointed and round arched windows; circular window under front gable; two octagonal towers

**Alterations** Foundation raised (1918), stone foundation replaced with concrete block raised foundation; center entry constructed in 1942 and removed sometime after 1991; large sanctuary addition to the west (1961); raised east entry added sometime after 1991

## HISTORY

**Original Construction Date** 1898 per plaque

**Architect/Builder** Architect: William Arthur Bennett

**Associated Events, People, Dates** Listed in the National Register of Historic Places; significant dates for the building: 1898 & 1918. Interior has a Sullivanesque pressed metal ceiling. New sanctuary to the west constructed in 1961 (per cornerstone).

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

## Continuation Sheet

Address 9967 144th Street

Map Key D- 11



9967 144th Street\_Addition.jpg

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9970 144th Street

**Map Key** D- 12

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



9970 144th St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Split Level

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Brick, Vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Pyramidal (over two-story portion) & side gable (over one-story portion)

**Window Type & Materials** Wood 1/1; Chicago window

**Porch**

**Architectural Details** Wood paneled door; second floor overhangs the ground floor

**Alterations**

## HISTORY

**Original Construction Date** c1965

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9976 144th Street

**Map Key** D- 13

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9976 144th St\_3.jpg

## DESCRIPTION

### **Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Upright-and-Wing

**Number of Stories** 2

### **Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with side gable wing

**Window Type & Materials** 1/1 replacement windows; 6/6 replacement windows with applied muntins

**Porch** Integral porch under side gabled roof of the side wing; screened with turned posts and balusters

**Architectural Details** Paired window at first floor; squared window hoods; gabled roof dormers

**Alterations** Synthetic siding; windows have been replaced; gabled roof dormers have been added since 1991; porch enclosed

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9809 145th Place

**Map Key** E- 1

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9809 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Not visible

**Walls** Brick, stone, wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Not visible: 6/6, single- light, multi-light, glass block

**Porch** Recessed front entry under main roof

**Architectural Details** Two large interior brick chimneys; attached garage

**Alterations** Non-original front door, some windows appear to be non-original

## HISTORY

**Original Construction Date** c1965

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9827 145th Place

**Map Key** E- 2

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9827 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Not visible

**Walls** Wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: 2/2 (horizontal), fixed

**Porch** Integral porch under main roof with segmental arches between porch supports; wood door with large light in upper panel

**Architectural Details** Interior chimney, attached garage

**Alterations**

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9840 145th Place

**Map Key** E- 3

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9840 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Minimal Traditional, altered

**Number of Stories** 1

**Materials**

**Foundation** Not visible

**Walls** Brick, wood shingles under gables and on rear of house

**Roof** Asphalt shingles

**Roof Type** Side- gable

**Window Type & Materials** Synthetic: sliding

**Porch** Front gabled partial porch, screened; wood door with large oval light

**Architectural Details** Paired windows, end-wall exterior brick chimney, masonry window sills

**Alterations** Major addition in 1984 re: permit records

## HISTORY

**Original Construction Date** c1970

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9850 145th Place

**Map Key** E- 4

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9850 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete block

**Walls** Brick, vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: 2/2, Chicago window with 2/2 (horizontal) side windows

**Porch**

**Architectural Details** Enclosed breezeway between house and garage; attached garage; roll top awnings over the windows; interior brick chimney

**Alterations** Wood step with metal railings; vertical wood siding appears to be newer

## HISTORY

**Original Construction Date** c1945

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9855 145th Place

**Map Key** E- 5

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9855 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Contemporary

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Unknown: fixed, 1/1, sliding

**Porch**

**Architectural Details** Exterior brick chimney at end wall; attached garage facing the street; large wall bay of windows from grade to roofline

**Alterations**

## HISTORY

**Original Construction Date** 1966

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9856 145th Place

**Map Key** E- 6

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9856 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Hipped

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Not visible: 1/1; Chicago window

**Porch** Hipped, open, partial porch with wood posts; paneled door with 9 divided lights in upper panel

**Architectural Details** Interior brick chimney; attached garage

**Alterations**

## HISTORY

**Original Construction Date** c1995

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9866 145th Place

**Map Key** E- 7

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9866 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoTudor

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Brick, synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable with continuous sloped roof to the garage

**Window Type & Materials** Wood & synthetic: casements

**Porch** Side entrance door under gable porch roof with wood column

**Architectural Details** Decorative window hoods at first floor; large exterior end-wall brick chimney; attached garage; distinctive sloped roof from house ridgeline to the end of the attached garage

**Alterations**

## HISTORY

**Original Construction Date** 1970-re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9876 145th Place

**Map Key** E- 8

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9876 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Tudor Revival

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Brick, fieldstone, wood shingles in dormer

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Wood: 6/1; Replacement: 1/1, bay window with picture window

**Porch** Vertical, arched wood batten door with small rectangular light in upper part of door

**Architectural Details** Brick set in a rusticated bond; large, brick, exterior end-wall chimney; stone window sills; multiple projecting gables at the front; gabled wing at the side

**Alterations** Windows replaced at the first floor, first floor of side wing has been altered and faced with a concrete finish

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9877 145th Place

**Map Key** E- 9

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9877 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoColonial

**Number of Stories** 2 1/2

**Materials**

**Foundation** Not visible

**Walls** Brick, wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Synthetic: 4/4, 6/6 simulated divided lights

**Porch** Partial, open entry porch with square columns and balustraded deck above

**Architectural Details** Multiple gabled roof dormers; paired windows; attached garage with gabled dormer; shutters

**Alterations**

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9886 145th Place

**Map Key** E- 10

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9886 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoMansard

**Number of Stories** 2

**Materials**

**Foundation** Not visible/raised foundation of brick

**Walls** Brick, vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Mansard/Hip combination

**Window Type & Materials** Wood: casement

**Porch** Main entrance located in enclosed breezeway between house and garage

**Architectural Details** Suspended breezeway, enclosed, connecting the house to the garage; exterior end-wall brick chimney

**Alterations**

## HISTORY

**Original Construction Date** c1985

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9887 145th Place

**Map Key** E- 11

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9887 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Contemporary

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Wood: single light

**Porch** Open entrance porch with wood posts and balustraded deck above

**Architectural Details** Ribbon of casement windows at the first floor; attached garage the faces the street

**Alterations** Second floor addition over the garage

## HISTORY

**Original Construction Date** c1975

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9901 145th Place

**Map Key** E- 12

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9901 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Tudor Revival

**Number of Stories** 1 1/2

**Materials**

**Foundation** Not visible

**Walls** Brick, stucco, half-timbering

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: 6/6; Synthetic: single light, 6/6 simulated divided lights

**Porch**

**Architectural Details** Center massing with an angled wing at each end; gabled roof dormers, expanses of windows across the front of the house; garage/coach house attached via an enclosed breezeway

**Alterations**

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9906 145th Place

**Map Key** E- 13

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9906 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable, altered

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding, Lannon stone

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Synthetic: 1/1, casement

**Porch**

**Architectural Details** Second floor overhangs first floor; squared Lannon stone projecting bay at the first floor that meets the wall plane of the projecting second floor; interior brick chimney

**Alterations** Second floor addition

## HISTORY

**Original Construction Date** c1970; addition/alteration 2005: permit **Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9907 145th Place

**Map Key** E- 14

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9907 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Dutch Colonial

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Brick

**Roof** Asphalt shingles

**Roof Type** Gambrel and gable wing

**Window Type & Materials** Wood: 6/6; Synthetic: 6/6 with simulated divided lights

**Porch**

**Architectural Details** Interior brick chimney; Colonial Revival door surround; side wing, roof dormers; shutters

**Alterations**

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9908 145th Place

**Map Key** E- 15

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9908 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Wood: 2/2 (horizontal); Chicago window with 2/2 (horizontal) muntins at side windows

**Porch** Front door recessed under the main roof, concrete steps, wood paneled door with horizontal lights

**Architectural Details** Interior brick chimney, shutters; attached garage

**Alterations** New wood garage door (both overhead and secondary pedestrian door)

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9911 145th Place

**Map Key** E- 16

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9911 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoColonial

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: divided light arched window; Synthetic: 6/6, 8/12, Muli/4 simulated divided lights

**Porch** Integral porch, open, wrap around, hipped roof, turned posts, square balusters

**Architectural Details** Interior brick chimney; roof dormers at middle section of the house

**Alterations** Second floor garage addition; two-story addition to the side that is sited at a right angle and extends forward from the original house

## HISTORY

**Original Construction Date** 1985-re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9912 145th Place

**Map Key** E- 17

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9912 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick, Lannon stone

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Wood: 2/2 (horizontal muntins)

**Porch** Main entry at the interior corner of the house with the main roof overhanging the entrance steps; concrete deck & steps, metal posts

**Architectural Details** Paneled door with three horizontal lights; attached garage; interior brick chimney

**Alterations**

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9931 145th Place

**Map Key** E- 18

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9931 145th Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoTraditional

**Number of Stories** 2 1/2

**Materials**

**Foundation** Concrete

**Walls** Brick, stucco

**Roof** Asphalt shingles

**Roof Type** Multiple hip

**Window Type & Materials** Synthetic: 8/8, 6/6, 4/4, 4/6, 8/12 simulated divided lights; octagonal

**Porch** Open, wrap around porch with hipped roof, round columns, turned balusters and newels

**Architectural Details** Profusion of roof forms including multiple hips, gables, conical, and flared hip; brick wall surface at the first floor, stucco at the second floor, first floor windows have limestone sills; attached garage with gabled roof dormer

**Alterations**

## HISTORY

**Original Construction Date** 1998-re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9853 145th Street

**Map Key** F- 1

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9853 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Hipped, altered

**Number of Stories** 1 w/ 2-story addition

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Wood: Chicago window with fixed light and 6/1; Vinyl: 6/1 with simulated divided lights, paired; octagonal

**Porch** Partial open porch with hipped roof, wood columns and balusters; wood paneled door with 12 divided lights in the upper portion

**Architectural Details** Large interior brick chimney

**Alterations** 2-story rear addition with hipped roof; 1-story addition at the front of the house; altered/addition 2001-re: permit records

## HISTORY

**Original Construction Date** c1980

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9856 145th Street

**Map Key** F- 2

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9856 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1

**Materials**

**Foundation** Parged with concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Chicago window with fixed light and casements; 1/1

**Porch** Concrete steps and metal railing; non-original panel door with single etched glass light

**Architectural Details**

**Alterations** Siding, door, windows

## HISTORY

**Original Construction Date** c1960

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9858 145th Street

**Map Key** F- 3

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9858 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Hipped

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Brick and vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Chicago window with fixed light and 1/1 windows to each side; 1/1 (paired throughout)

**Porch**

**Architectural Details** The house is made up of two hipped forms: at the front it is 1-story, the rear hipped form is 2-stories. Stone window sills; side entrance; short wall extension with lantern mounted on top

**Alterations**

## HISTORY

**Original Construction Date** c1970

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9862 145th Street

**Map Key** F- 4

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9862 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Gable (with flat roof over side wing)

**Window Type & Materials** Non-original 6/6 and 8/8 simulated divided lights, paired

**Porch** Open, partial porch with concrete foundation and deck, metal railings and paneled door

**Architectural Details** Bay window at the side of the house

**Alterations** Side entrance wing with flat roof and interior brick chimney

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9863 145th Street

**Map Key** F- 5

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9863 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch, altered

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Multi-hipped with front gable end

**Window Type & Materials** Synthetic: 1/1, paired, Chicago window

**Porch** Wide, open deck in front of the door, door recessed under hipped roof

**Architectural Details** Interior brick chimney; attached garage

**Alterations** The roof appears to have been altered and extended to incorporate the garage.

## HISTORY

**Original Construction Date** c1960; altered/addition 1985-re:permit **Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9868 145th Street

**Map Key** F- 6

**Common Name**

**Historic Name**

**Current Use** Vacant

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9868 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding; vertical siding in the gable ends

**Roof** Asphalt shingles

**Roof Type** Side- gable with projecting front gable over the door

**Window Type & Materials** Metal: Chicago window, 1/1, sliding

**Porch**

**Architectural Details**

**Alterations** Siding; windows; non-original panel door with arched lights in the top portion

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9873 145th Street

**Map Key** F- 7

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9873 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick and wood siding

**Roof** Asphalt shingles

**Roof Type** Side- gable

**Window Type & Materials** Wood: fixed, awning, 2/2 (horizontal); also 1/1 of unknown material

**Porch** Partial integral porch, open with concrete deck and steps and metal railing; paneled door with single square light at the top

**Architectural Details** Wide interior brick chimney; integral garage

**Alterations**

## HISTORY

**Original Construction Date** c1945

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9876 145th Street

**Map Key** F- 8

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9876 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey - house since demolished & replaced with this house

**Architectural Type/Style** NeoTraditional

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Brick, rusticated limestone

**Roof** Asphalt shingles

**Roof Type** Complex with multiple levels of hipped, gabled and hexagonal roof forms

**Window Type & Materials** Synthetic with simulated divided lights: Casements, fixed, octagonal, transoms (arched & rectangular), oval, bay

**Porch** Gabled entrance projection with the door recessed within; paneled door with etched glass, matching sidelights, and oversized transom

**Architectural Details** Profusion of projecting gables, and bays; the brick and limestone are interchangably used on various wall surfaces, window surrounds are accented with contrasting wall material and accented with a keystone; the gables have a short gable-end return detail; the garage is attached, extending from the house toward the street at a right angle and with a large hexagonal dormer

**Alterations**

## HISTORY

**Original Construction Date** 2002-re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9877 145th Street

**Map Key** F- 9

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9877 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Minimal Traditional

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Cross- gable

**Window Type & Materials** Wood: round arch with divided lights; Unknown material: casements, 1/1, and single light (with diamond pattern simulated divided lights)

**Porch**

**Architectural Details** Multiple projecting gables at the front of the house; interior brick chimney; wood batten door with three vertically staggered lights toward the top; shutters.

**Alterations** Siding, windows, handicapped accessible ramp at the front of the house

## HISTORY

**Original Construction Date** c1945

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9880 145th Street

**Map Key** F- 10

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9880 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoTraditional

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Brick and rusticated limestone

**Roof** Asphalt shingles

**Roof Type** Complex with multiple levels of hipped, gabled and arched roof forms

**Window Type & Materials** Synthetic with simulated divided lights: casements, fixed, bay, transoms (arched and rectangular), oval

**Porch** Gabled entrance projection with the door recessed within; paneled door with etched glass, matching sidelights, and oversized transom

**Architectural Details** Profusion of projecting gables and bays; the brick and limestone are interchangeably used on various wall surfaces, window surrounds are accented with contrasting wall material and detailed with a keystone; the gables have a short gable-end return detail; the garage is attached, extending from the house toward the street at a right angle and with a large arched dormer.

**Alterations**

## HISTORY

**Original Construction Date** 2004-re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9886 145th Street

**Map Key** F- 11

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9886 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable, altered

**Number of Stories** 2

**Materials**

**Foundation** Concrete block; porch: concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable and shed

**Window Type & Materials** Wood & synthetic: Chicago window, 1/1, sliding, casement, octagonal

**Porch** Gabled with turned posts, concrete deck and steps; door with diamond shaped lights at the top

**Architectural Details**

**Alterations** Rear two-story addition, gabled entry addition, enclosed porch, siding, windows

## HISTORY

**Original Construction Date** c1940

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9887 145th Street

**Map Key** F- 12

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9887 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: 4/1, 3/1, paired; glass block

**Porch** Small open porch at the gabled projecting entrance; turned posts under a metal awning and balusters; paneled front door; concrete steps

**Architectural Details** Interior brick chimney

**Alterations** Siding, porch

## HISTORY

**Original Construction Date** c1945; addition 1993 re: permit records **Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9889 145th Street

**Map Key** F- 13

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9889 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick, vertical board siding

**Roof** Asphalt shingles

**Roof Type** Gable, shed addition; attached garage has a hipped roof

**Window Type & Materials** Wood: Chicago window, 1/1, 2/2 (horizontal muntins)

**Porch**

**Architectural Details** Large interior brick chimney; attached garage; paneled front door with divided lights in upper half with matching sidelights

**Alterations** Two front additions: front gabled and shed

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9890 145th Street

**Map Key** F- 14

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9890 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoTraditional

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Brick, rusticated limestone, synthetic siding

**Roof** Asphalt shingles

**Roof Type** Complex with multiple levels of hipped, gabled and hexagonal roof forms

**Window Type & Materials** Synthetic with simulated divided lights: casements, fixed, octagonal, arched transoms, oval

**Porch** Recessed entry with a shed roof; paneled door with etched glass and matching sidelights

**Architectural Details** Profusion of projecting gables, bays and dormers; the brick, limestone and synthetic siding are interchangeably used on various wall surfaces, window surrounds are accented with a keystone and some surrounds are of contrasting materials; gables have short gable-end returns; garage faces the street and has a projecting gabled wall dormer

**Alterations**

## HISTORY

**Original Construction Date** 2004-re: permit records; finished 2007      **Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9894 145th Street

**Map Key** F- 15

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9894 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch, altered

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Brick and vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood, Chicago window, casement, bay window

**Porch**

**Architectural Details** Attached garage; wood front door with sidelights

**Alterations** Second floor addition; dry-vit window surround at first floor bay with keystone ornament; boxed eaves with synthetic siding

## HISTORY

**Original Construction Date** c1960

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9923 145th Street

**Map Key** F- 16

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9923 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gabled Ell, altered

**Number of Stories** 2

**Materials**

**Foundation** Concrete block

**Walls** Brick and synthetic siding

**Roof** Asphalt shingles

**Roof Type** Cross gable

**Window Type & Materials** Wood: 2/2 (horizontal); Vinyl: 6/6, casement, arched, with simulated divided lights

**Porch** Partial open porch with shed roof, concrete steps and landing with 2x4's supporting the roof; wood paneled door with one etched glass light

**Architectural Details**

**Alterations** One-story brick house altered with the addition of a second floor; windows; porch. Altered 2005- re: permit records

## HISTORY

**Original Construction Date** c1940

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9925 145th Street

**Map Key** F- 17

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9925 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick and vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: 1/1; picture window; awning

**Porch** Non-original open deck with turned posts and balusters. Existing roof overhangs part of the deck

**Architectural Details**

**Alterations** Front deck; wall mounted flower box; rear addition with vertical wood siding

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9926 145th Street

**Map Key** F- 18

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9926 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Tudor Revival

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Brick with rusticated limestone quoins, log siding

**Roof** Asphalt shingle

**Roof Type** Hipped with cross gables

**Window Type & Materials** Chicago window with 4/4 side windows at the bay, 6/6, and non-original windows at the second floor with 6/6 simulated divided lights

**Porch**

**Architectural Details** Large side chimney of rusticated limestone; projecting gabled entrance with wood paneled door; gabled roof dormers with log siding, the same log siding at the gable end at the chimney.

**Alterations** Replacement windows at the second floor

## HISTORY

**Original Construction Date** c1940

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9927 145th Street

**Map Key** F- 19

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9927 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Minimal Traditional

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Stone, vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Cross- gable

**Window Type & Materials** Wood: Chicago window, 2/2 (horizontal), awning windows, paired

**Porch**

**Architectural Details** Wood paneled door; limestone wall surface with wood siding under the gable; limestone window sills; smaller interior chimney

**Alterations**

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9933 145th Street

**Map Key** F- 20

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9933 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Minimal Traditional

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick, synthetic siding

**Roof** Asphalt shingles

**Roof Type** Cross- gable

**Window Type & Materials** Wood: Chicago window, 4/1, 6/1, paired

**Porch**

**Architectural Details** Large interior brick chimney; doors are wood paneled with upper divided lights; attached garage; secondary entrance adjacent to the garage

**Alterations**

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9940 145th Street

**Map Key** F- 21

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9940 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Unknown material: Chicago window, 1/1, sliding

**Porch** Open, wide concrete deck with metal railing

**Architectural Details** Interior brick chimney; wood paneled door; garage with hipped roof, attached via enclosed breezeway; secondary entrance adjacent to the garage

**Alterations** Siding, deck

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9949 145th Street

**Map Key** F- 22

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



9949 145th Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Split Level

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Brick, synthetic vertical siding

**Roof** Asphalt shingles

**Roof Type** Pyramidal & gabled

**Window Type & Materials** Casement windows, unknown material

**Porch**

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date** 1985-re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14300 Beacon Avenue

**Map Key** G- 1

**Common Name** Beacon Auto Parts

**Historic Name**

**Current Use** Vacant

**Historic Use** Commercial

**Integrity** Medium

**Condition** Fair

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14300 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** 20th Century Commercial / Storefront

**Number of Stories** 1

**Materials**

**Foundation** Not Visible

**Walls** Brick; Vertical wood siding

**Roof** Built-up Bituminous

**Roof Type** Bow truss

**Window Type & Materials** Wood, fixed divided light with transom; some windows boarded over

**Porch**

**Architectural Details** Stepped false-front facade outlined with brick soldier course

**Alterations** A narrow profile false-mansard roof; the portico and door are not original; there is an addition to the side

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates** Constructed as an automobile dealership by Walter Schussler. The addition was constructed for use as a service garage. The building served multiple subsequent purposes and was later used as an auto parts store. (Source: Oral history compiled by Joyce Lahti)

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14300 Beacon Avenue

**Map Key** G- 1

**Common Name**

**Historic Name**

**Current Use** Demolished

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

Individual

Old Orland Historic  
District

**National Register**

Individual



14300 Beacon Ave\_2.jpg

## DESCRIPTION

### **Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

### **Architectural Type/Style**

**Number of Stories**

### **Materials**

**Foundation**

**Walls**

**Roof**

**Roof Type**

**Window Type & Materials**

**Porch**

### **Architectural Details**

### **Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14309 Beacon Avenue

**Map Key** G- 2

**Common Name** Mitchell's Flowers

**Historic Name**

**Current Use** Retail

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14309 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gabled Ell, altered

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Wood panels with a vertical board pattern

**Roof** Asphalt shingles

**Roof Type** Cross gable

**Window Type & Materials** Wood: fixed, 1/1; Casements of unknown material

**Porch** Partial porch which has been altered and enlarged; wide side-entry steps are covered by a partial wall, open at the top

**Architectural Details** Smaller interior brick chimney toward the rear

**Alterations** Multiple additions toward the rear; siding, porch, windows, connected to adjacent building via an upper-story enclosed stair

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14314 Beacon Avenue

**Map Key** G- 3

**Common Name** Beacon Ave. Antiques

**Historic Name**

**Current Use** Retail/Residential

**Historic Use**

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14314 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Side Gable

**Number of Stories** 2

**Materials**

**Foundation** Brick; addition is concrete block

**Walls** Vertical board; synthetic siding; synthetic shingles

**Roof** Asphalt shingles

**Roof Type** Side Gable; hipped over porch

**Window Type & Materials** Wood double-hung; aluminum storefronts

**Porch** Side porch, open at the second floor, enclosed at the first floor

**Architectural Details**

**Alterations** Shed roof of wood shingles added over storefront windows; siding altered; gabled side addition; storefronts have been altered

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14315 Beacon Avenue

**Map Key** G- 4

**Common Name** Touch of Class Pet Grooming

**Historic Name**

**Current Use** Commercial/Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14315 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Folk Victorian

**Number of Stories** 2

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable; hipped roof over porch

**Window Type & Materials** Wood, double-hung with 2/2 verticle lights; metal picture window; Queen Anne window with transom at the side of the house

**Porch** "L" shaped porch with turned wood posts, squared balusters, spindlework porch detailing, wide wood steps and hipped roof

**Architectural Details** Original decorative window hoods and casing with incised design, bullseye corner blocks and stepped wood window hood; same wood detail surrounds the front door; interior brick chimney

**Alterations** Siding altered; some windows replaced

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates** Originally home to August Witt, the local undertaker. (Source: Oral history compiled by Joyce Lahti)

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14316 Beacon Avenue

**Map Key** G- 5

**Common Name** Old Bank Antiques

**Historic Name** Orland State Bank

**Current Use** Retail/Residential

**Historic Use** Commercial/Residential

**Integrity** High

**Condition** Excellent

## Local Landmark

**Individual** Yes

**Old Orland Historic District** Contributing

## National Register

**Individual** No



14316 Beacon\_7.jpg

## DESCRIPTION

### Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** 20th Century Commercial / Italianate

**Number of Stories** 2

### Materials

**Foundation** Parged

**Walls** Brick

**Roof** Built-up bituminous

**Roof Type** Flat

**Window Type & Materials** Wood double-hung 1/1 light; wood fixed; transoms with divided light pattern

### Porch

**Architectural Details** Limestone sills and lintels; limestone ornament at parapet; corbelled brick at parapet capped with limestone; corbelled chimney detail at side of building; painted cornice at first floor; original wood door frames; historic door to commercial space; original wood windows

### Alterations

## HISTORY

**Original Construction Date** 1920 per limestone marker

**Architect/Builder**

**Associated Events, People, Dates** Housed the Orland State Bank from 1920 until 1956 when the bank moved to a new building. The upstairs was used as the Central Exchange office for the Chicago Telephone Company for the Orland area until it moved to Palos park (Source: Oral history compiled by Joyce Lahti).

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14319 Beacon Avenue

**Map Key** G- 6

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14319 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Hipped

**Number of Stories** 2

**Materials**

**Foundation** Limestone

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped with gabled wing

**Window Type & Materials** Wood: 1/1, 2/2, fixed picture window

**Porch** Partial, open porch with hipped roof, turned posts, wide wood steps, limestone foundation piers; 6-paneled wood doors

**Architectural Details** Hipped portion has porch and unique second story squared bay, angled across the corner of the house; front- gabled, one-story wing has a squared bay with hipped roof and picture window. The entrance to the wing is under the porch, adjacent to the primary entrance.

**Alterations** Siding altered, some windows replaced

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates** First owner was Dr. Walter R. Schussler (mayor from 1925-1929). South portion, first floor, was doctor's office; family lived above and in north portion. Walter Jr., who also lived in the house, was mayor from 1941 to 1965.

**Surveyor** PV/DE

**Date** 3/19/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14320-24 Beacon Avenue

**Map Key** G- 7

**Common Name**

**Historic Name**

**Current Use** Retail/Residential

**Historic Use** Commercial

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14320-24 Beacon\_5.jpg

## DESCRIPTION

### **Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** 19th Century Commercial / Storefront

**Number of Stories** 2

### **Materials**

**Foundation** Not visible

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Front gable behind a false front parapet; side addition has a cross gable roof

**Window Type & Materials** Wood 1/1 double hung; metal sliding

**Porch** Addition has an open porch at the first floor and an open entry porch at the second floor

**Architectural Details** False front facade; wood door frame and windows

**Alterations** Synthetic siding; first floor windows altered; residential wing at the side

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14329 Beacon Avenue

**Map Key** G- 8

**Common Name** Digital Photo and Video

**Historic Name**

**Current Use** Commercial

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14329 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1 1/2

**Materials**

**Foundation** Parged

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Front gable; hipped over porch

**Window Type & Materials** Wood 1/1 double-hung; wood picture window; original windows at the side include small sash with three verticle divided lights

**Porch** Open wood porch with brick piers, wood deck, round columns and hipped roof

**Architectural Details**

**Alterations** First floor window has been altered; interior chimney is new brick

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14330 Beacon Avenue

**Map Key** G- 9

**Common Name** Anna B's Antiques

**Historic Name**

**Current Use** Retail

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14330 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Folk Victorian

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; wood shingle

**Roof** Wood shingle

**Roof Type** Front gable with hipped porch

**Window Type & Materials** Wood 1/1 light double-hung windows; Queen Anne windows with colored glass transoms

**Porch** Open wood porch with hipped roof with center gable; turned posts, balusters and spindlework; wood doors; formed concrete block piers

**Architectural Details** Wood clapboard with decorative shingles in gables; gingerbread ornament under front upper gable; side gabled bays on each side

**Alterations** Parged interior chimney

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates** This house was known as the Gunderman home (Source: Oral history compiled by Joyce Lahti).

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14332 Beacon Avenue

**Map Key** G- 10

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14332 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Front facing gables with lower cross gable

**Window Type & Materials** Wood: 1/1, casements, transoms; Synthetic: 1/1

**Porch** Open porch with shed roof, grade level concrete deck and wood corner posts; front door not visible

**Architectural Details** Two identical front-gable wings connected by a lower cross gable. The connecting gabled section has a center entry with a pair of windows at each side. Each wing has a ribbon of 5 windows, each with a transom. These windows are centered in the wall; centered under each gable is a single 1/1 window. Each wing has in interior chimney of concrete masonry

**Alterations**

## HISTORY

**Original Construction Date** c1940 (btwn 1931-1949Sanborn)

**Architect/Builder**

**Associated Events, People, Dates** Remnant foundation at front of the lot is from an early commercial building with residential above, that burned in February of 1931.

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14339 Beacon Avenue

**Map Key** G- 11

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14339 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Folk Victorian

**Number of Stories** 1 1/2

**Materials**

**Foundation** Parged; covered with plywood

**Walls** Wood clapboard; wood shingles

**Roof** Asphalt shingles

**Roof Type** Front gable; hipped porch and bays

**Window Type & Materials** Wood, 2/2 light. double hung; wood, 1/1 light double hung; wood 1/1 single hung

**Porch** Wood porch open at door only; turned column, wood steps and deck

**Architectural Details** Wood clapboard siding with decorative wood shingles; side bay with hipped roof; some windows have original wood window trim at the top; front door has original transom window

**Alterations** Decorative shingles under gable installed sometime after 1991, source: 1991 Residential Survey photograph

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates** Early residents of this home was the Kotts family. At one time part of the first floor was used as a Telephone Exchange for the Northwestern Telephone Company which competed with the Chicago Telephone Company (Source: Oral history compiled by Joyce Lahti).

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14342 Beacon Avenue

**Map Key** G- 12

**Common Name**

**Historic Name**

**Current Use** Commercial

**Historic Use**

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14342 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoMansard, altered

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Deck

**Window Type & Materials** Wood: Multi-light with horizontal muntins; 2/2 (horizontal), 2/2 (vertical); 3/1; Synthetic: Chicago window with 1/1 side windows

**Porch**

**Architectural Details** Wood storm windows; the front door retains original wood transom window with one vertical muntin

**Alterations** Roof, siding, windows

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14343 Beacon Avenue

**Map Key** G- 13

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14343 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 2 1/2

**Materials**

**Foundation** Not visible

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable with shed dormer

**Window Type & Materials** Wood: 1/1, casement. Non-original: 6/6 with simulated divided lights

**Porch**

**Architectural Details** Hexagonal bay addition at the side; full-length roof dormer at the side with a shed roof; non-original front door with large oval light

**Alterations** Siding, windows, bay, dormer, front door

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14401 Beacon Avenue

**Map Key** G- 14

**Common Name**

**Historic Name**

**Current Use** Vacant lot

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14401 Beacon\_no house.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

2005 Residential Survey

**Architectural Type/Style**

**Number of Stories**

**Materials**

**Foundation**

**Walls**

**Roof**

**Roof Type**

**Window Type & Materials**

**Porch**

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor**

**Date**



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14403 Beacon Avenue

**Map Key** G- 15

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14403 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gable-Front / Altered

**Number of Stories** 2 1/2

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with hipped porch

**Window Type & Materials** Replacements: 6/6 light, double-hung; 1/1 light double-hung; center fixed window with narrow casements to each side divided by four horizontal muntins

**Porch** Open wood porch with turned posts and tall railing

**Architectural Details** None of the details of the original house remain

**Alterations** Original building was a one-story, front gable house and was documented as such in the 1991 Residential Survey. Since that time, the building has been significantly altered so that it no longer retains the height, scale, materials or architectural details of the original

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates** Original one-story house was the Winterberg Photography Studio, established pre-1904.

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14407 Beacon Avenue

**Map Key** G- 16

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14407 Beacon\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Craftsman

**Number of Stories** 1 1/2

**Materials**

**Foundation** Brick on concrete

**Walls** Wood clapboard; verticle wood boards at dormer

**Roof** Asphalt shingle

**Roof Type** Hipped

**Window Type & Materials** Wood 3/1 double-hung windows (upper windows have 3 verticle muntins)

**Porch** Enclosed front porch with tall brick piers; concrete steps

**Architectural Details** Wide eaves; side bay; hipped dormer with two hinged, single, wood windows; interior brick chimney; ganged windows at the front are grouped in threes

**Alterations** Front portico addition with gabled roof; porch enclosed

## HISTORY

**Original Construction Date** c1915

**Architect/Builder**

**Associated Events, People, Dates** Built by Charley Grange; his daughter Lois lived here with her husband Joe Novack (Source: Oral history compiled by Joyce Lahti).

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14415 Beacon Avenue

**Map Key** G- 17

**Common Name** Old Village Hall

**Historic Name** Orland Park Village Hall

**Current Use** Municipal

**Historic Use** Municipal

**Integrity** High

**Condition** Good

## Local Landmark

**Individual** No

**Old Orland Historic District** Non-contributing

## National Register

**Individual** No



14427 Beacon Avenue.jpg

## DESCRIPTION

### Inclusion in Previous Surveys

**Architectural Type/Style** Minimal Traditional

**Number of Stories** 1

### Materials

**Foundation** Concrete

**Walls** Brick, Lannon stone, aluminum siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: Chicago window, 1/1 & Chicago window with 2/2; 1/1; 2/2 paired

### Porch

**Architectural Details** Stone window sills; two front gable wings with lower walls of Lannon stone, upper walls of brick with limestone beltcourse and siding under the gables. The main entrance is at the north wing: a pair of aluminum-framed glass doors with a wide, squared stone surround. Wings joined by a lower, recessed connector with overhead garage door for large vehicles.

### Alterations

## HISTORY

**Original Construction Date** 1960

**Architect/Builder**

**Associated Events, People, Dates** This has been the site of the Village Hall since the 1890s. The original (smaller) building was demolished to construct this building; the offices of the Village Hall moved into a new complex on Ravinia Avenue in 1989.

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14435 Beacon Avenue

**Map Key** G- 18

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14435 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey

**Architectural Type/Style** Folk Victorian

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block; concrete block

**Walls** Wood siding and shingles

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Wood: 1/1, fixed, picture window with transom,

**Porch** Open, partial porch with hipped roof, and wood elements: turned posts, balusters and spindlework frieze, deck & steps; wood paneled door

**Architectural Details** Gabled bay adjacent to the front porch; shingles in the gables and on the lower wall area of the bay; limestone retaining wall

**Alterations** Gabled roof dormers (c1980), windows replaced (c1980), foundation replaced (probably c1920); garage/coach house constructed c1980

## HISTORY

**Original Construction Date** pre 1894 per owner

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14439 Beacon Avenue

**Map Key** G- 19

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14439 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Synthetic: 1/1 (some paired), Chicago window with 1/1 at each side

**Porch**

**Architectural Details** Partially below grade built-in garage under the house at the southwest corner; limestone retaining wall

**Alterations** Full second floor added c2005; curved concrete steps and metal railing to front door; front door with large oval light in upper portion; limestone retaining wall has been mortared.

## HISTORY

**Original Construction Date** c1950, altered 2005

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14465 Beacon Avenue

**Map Key** G- 20

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14465 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Minimal Traditional

**Number of Stories** 1

**Materials**

**Foundation** Concrete block

**Walls** Wood siding

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Wood: 2/2 (horizontal)

**Porch** Open concrete steps with metal railing; front door is wood with 24 square panels

**Architectural Details** Interior brick chimney

**Alterations**

## HISTORY

**Original Construction Date** c1945

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14466 Beacon Avenue

**Map Key** G- 21

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14466 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-on-Hip

**Number of Stories** 1

**Materials**

**Foundation** Concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable, hip

**Window Type & Materials** Unknown: 1/1

**Porch** Open deck with wood railing; panel door with round arch light

**Architectural Details** Interior chimney

**Alterations** Siding; chimney covered with synthetic siding; gabled addition at the front of the house

## HISTORY

**Original Construction Date** c1930

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14472 Beacon Avenue

**Map Key** G- 22

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14472 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Unknown: 1/1, sliding, fixed

**Porch**

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date** c1960

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14475 Beacon Avenue

**Map Key** G- 23

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14475 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable

**Number of Stories** 1

**Materials**

**Foundation** Concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Side- gable

**Window Type & Materials** Wood: 1/1, 4/4; Non-original 6/6 simulated divided light

**Porch** Concrete steps, metal posts and railings, vinyl paneled door, metal awning roof

**Architectural Details** Windows that wrap the corners of the front facade

**Alterations**

## HISTORY

**Original Construction Date** c1955

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14501 Beacon Avenue

**Map Key** G- 24

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14501 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Colonial Revival

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Side- gable

**Window Type & Materials** Wood: 6/6, 8/8

**Porch** Concrete steps; non-original door

**Architectural Details** Gabled projecting entrance; two gabled roof dormers; interior brick chimney; rear 1-story wing

**Alterations** Siding

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14506 Beacon Avenue

**Map Key** G- 25

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14506 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Split Level

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Brick, synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Wood & vinyl: 1/1, fixed

**Porch** Front deck with concrete deck and wood railing; wood paneled door with etched glass in large upper panel

**Architectural Details** Glass block and stone wall details

**Alterations**

## HISTORY

**Original Construction Date** c1965

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14512 Beacon Avenue

**Map Key** G- 26

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14512 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Dutch Colonial

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Wood siding

**Roof** Asphalt shingles

**Roof Type** Gambrel with full-width shed dormer

**Window Type & Materials** Wood: 6/1; 3-light

**Porch** Entrance portico with eyebrow roof, round columns, wood deck & steps and turned balustrade

**Architectural Details** Exterior end-wall chimney with limestone details; flower box brackets under the windows

**Alterations**

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14515 Beacon Avenue

**Map Key** G- 27

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14515 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable

**Number of Stories** 1 1/2

**Materials**

**Foundation** Parged

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Wood: 6/6

**Porch**

**Architectural Details** Large end-wall limestone chimney; projecting gabled area at the front where the door is; gabled roof dormer

**Alterations** Rear 1-story addition with roof deck

## HISTORY

**Original Construction Date** c1930

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14525 Beacon Avenue

**Map Key** G- 28

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14525 Beacon Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Red brick at front, concrete block at sides

**Walls** Yellow brick at front, synthetic siding at the sides

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: 2/2, 1/1, Chicago window

**Porch** Wide roof overhang projects over the front door; secondary entrance in the enclosed breezeway between the house and the garage

**Architectural Details** Limestone belt under window; interior chimney, end wall chimney; front-gabled garage connected to the house by a lower side gabled breezeway; wood paneled door with small square lights at the top

**Alterations** Rear 1-story addition

## HISTORY

**Original Construction Date** c1960

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14310 Brook Avenue

**Map Key** H- 1

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14310 Brook Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Bungalow

**Number of Stories** 1 1/2

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Wood 1/1 & single light (in the dormer)

**Porch**

**Architectural Details** Hipped dormer

**Alterations** Siding; Front steps & railings

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14350 Brook Avenue

**Map Key** H- 2

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14350 Brook Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side-Gable, altered to Minimal Traditional

**Number of Stories** 1

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Side- gable with gable wing and shed roof over front entry

**Window Type & Materials** Non-original 6/1 with simulated divided lights; Chicago window with 1/1 side windows; Side porch has original 3/1 wood windows

**Porch** Original gabled side porch (to the south); front entry has been enclosed and has a concrete stoop and metal railings

**Architectural Details**

**Alterations** The house has been altered to a minimal traditional with new foundation, rear gabled wing, new windows, a Colonial Revival window surround, shutters, an enclosed, projecting front entry, and synthetic siding.

## HISTORY

**Original Construction Date** 1894 (per owner); altered c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14414 First Avenue

**Map Key** I- 1

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14414 First Ave\_3.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gable-Front / altered

**Number of Stories** 1

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with multiple side gable additions

**Window Type & Materials** Metal 1/1 light double-hung

**Porch** Porch has been fully enclosed

**Architectural Details**

**Alterations** Synthetic siding; replacement windows; multiple additions at each side of the house; interior chimney

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates** This house was owned by John Creer who is also associated with the house next door (14420 First Avenue) (Source: Oral history compiled by Joyce Lahti). According to historic image at the OPHS, the Creer brothers (Jim, or his name was John?), and brother Howard owned Creer's Grocery and Butcher Shop on 143rd Street.

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14420 First Avenue

**Map Key** I- 2

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Fair

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14420 First Ave\_2.jpg

## DESCRIPTION

### **Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 2

### **Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Front gable; hipped porch

**Window Type & Materials** Wood 1/1 light double-hung; 2/2 vertical light double-hung; single hung

**Porch** Wood porch with turned posts, squared spindlework, replaced balusters; porch partially enclosed

**Architectural Details** Front door has original transom window

**Alterations** Synthetic siding; rear addition; steps at the side of the house to upper apartment

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates** Constructed as a single-family residence for the Kay family. When Mrs. Kay was widowed and her children were grown, she married John Creer (Source: Oral history compiled by Joyce Lahti).

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14431 First Avenue

**Map Key** I- 3

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14431 First Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete block & concrete

**Walls** Wood siding (wide width)

**Roof** Asphalt shingles

**Roof Type** Pyramidal front with gabled wing

**Window Type & Materials** 2/2; Chicago window with 2/2 side windows (2/2 windows have horizontal muntins)

**Porch**

**Architectural Details** Recessed door: wood door with horizontal glazed panels; interior brick chimney

**Alterations** Deck constructed at the front door with turned posts and balustrades.

## HISTORY

**Original Construction Date** c1960

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14438 First Avenue

**Map Key** I- 4

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14438 First Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Folk Victorian, altered

**Number of Stories** 1

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** 1/1, 2/2 wood; non-original wood picture window; inside porch are original 1/1 and Queen Anne windows

**Porch** Enclosed porch with ribbon windows and hipped roof

**Architectural Details** Small interior masonry chimney

**Alterations** Siding, windows, enclosed porch

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14439 First Avenue

**Map Key** I- 5

**Common Name**

**Historic Name**

**Current Use** Vacant Lot

**Historic Use**

**Integrity**

**Condition**

**Local Landmark**

Individual

Old Orland Historic  
District

**National Register**

Individual



14439 First Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style**

**Number of Stories**

**Materials**

Foundation

Walls

Roof

Roof Type

Window Type & Materials

Porch

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14327 Oak Place

**Map Key** J- 1

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14327 Oak Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 2

**Materials**

**Foundation** Limestone

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Gable

**Window Type & Materials** Non-original wood, 1/1

**Porch** Enclosed entry with pyramidal roof

**Architectural Details**

**Alterations** Siding, windows, enclosed entry, wood stairs to second floor with enclosed entry

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14331 Oak Place

**Map Key** J- 2

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14331 Oak Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 2

**Materials**

**Foundation** Limestone

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Non-original 1/1, vinyl

**Porch**

**Architectural Details** Entry is at the side; rectangular side bay with hipped roof and 1/1 windows

**Alterations** Siding, windows, gabled entry bay addition to the south (toward the rear)

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14335 Oak Place

**Map Key** J- 3

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14335 Oak Place.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gabled Ell

**Number of Stories** 2

**Materials**

**Foundation** Limestone, parged

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Cross- gable

**Window Type & Materials** Original 1/1 & 2/2 wood; Non-original artglass, 1/1 vinyl & octagonal with beveled glass

**Porch** Partially enclosed one-story porch inset into "L" with hipped roof

**Architectural Details** Front bay with hipped roof and Queen Anne window; interior brick chimney; side wing (to south) with shed roof

**Alterations** Siding, windows, part of original porch has been enclosed

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/13/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14406 Second Avenue

**Map Key** K- 1

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use**

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14406 2nd Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gabled Ell

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Wood siding

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Vinyl: oval, fixed and casement with simulated divided lights

**Porch** Open wrap-around porch with turned posts, wood deck and brick piers, hipped roof

**Architectural Details** Double, wood-paneled doors; exterior end-wall brick chimney

**Alterations** Additions in 1990 & 2007 re: permit records

## HISTORY

**Original Construction Date** 1990 altered/addition-re: permit records **Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14420 Second Avenue

**Map Key** K- 2

**Common Name**

**Historic Name** Cox House

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Fair

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14420 Second Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Side Gable

**Number of Stories** 2

**Materials**

**Foundation** Limestone

**Walls** Wood clapboard

**Roof** Asphalt shingles

**Roof Type** Side gable; hipped porch

**Window Type & Materials** Wood 2/2 light double-hung; Queen Anne window with leaded glass transom; Queen Anne storm window with leaded glass transom

**Porch** Open porch removed and one story bay additions were built on both sides of the center door; dentils remain; steps are not original

**Architectural Details** Side gable, center entry house, 2 rooms deep and 2 rooms wide; windows have simple wood hood ornament; dentils at the front porch. Property has an historic barn at the rear

**Alterations** Front porch removed, bay additions occupy the space to each side of center entry, non-original wood steps, wood framing at front door is original; non-original shutters; multiple, early, rear additions

## HISTORY

**Original Construction Date** 1880/ Village of Orland Park **Architect/Builder**

**Associated Events, People, Dates** Believed to be the first house built in Orland Park, source: Village of Orland Park

# Village of Orland Park, Illinois Historic Buildings Survey

## Continuation Sheet

**Address** 14420 Second Avenue

**Map Key** K- 2



14420 Second Ave\_barn.jpg

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14420 Second Avenue

**Map Key** K- 2

**Common Name**

**Historic Name** Cox House

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Excellent

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



1422 Second Avenue\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Side Gable

**Number of Stories** 2

**Materials**

**Foundation** Limestone, new

**Walls** Wood clapboard, new

**Roof** Asphalt shingles, new

**Roof Type** Side gable; hipped porch

**Window Type & Materials** Wood 2/2 light double-hung, new; Queen Anne window, new

**Porch** Steps and railings, new

**Architectural Details** Side gable, center entry house, 2 rooms deep and 2 rooms wide; windows have simple wood hood ornament; dentils at the front porch.

**Alterations** In 2007 all original building materials were removed including limestone foundation, clapboard siding, wood architectural ornament and wood windows. These elements were replaced with new to match original. Historic barn demolished for a new garage.

## HISTORY

**Original Construction Date** 1880; reconstructed 2006-07

**Architect/Builder**

**Associated Events, People, Dates** Believed to be the first house built in Orland Park, source: Village of Orland Park. In 2007 the house was significantly altered.

**Surveyor** PV

**Date** 03/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

## Continuation Sheet

**Address** 14420 Second Avenue

**Map Key** K- 2



14420 Second Ave\_side.jpg

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14421 Second Avenue

**Map Key** K- 3

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14421 Second Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Not visible

**Walls** Brick

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Wood: 1/1, casement

**Porch** Concrete step with metal railing

**Architectural Details** Limestone window sills; wood paneled door with large rectangular panel in upper half

**Alterations**

## HISTORY

**Original Construction Date** c1970

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 3/19/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14438 Second Avenue

**Map Key** K- 4

**Common Name** Doll House

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

### Local Landmark

**Individual** No

**Old Orland Historic District** Contributing

### National Register

**Individual** No



14438 Second Ave.jpg

## DESCRIPTION

### Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** National: Gable-Front

**Number of Stories** 1

### Materials

**Foundation** Parged

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Wood 1/1 light double-hung

### Porch

**Architectural Details** Windows and door have simple wood hood ornament; side entrance toward the rear

**Alterations** New front steps; new front door;

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14205 Union Avenue

**Map Key** L- 1

**Common Name** Schmaedeke Funeral Home

**Historic Name**

**Current Use** Commercial

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14205 Union Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Craftsman

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Wood shingles, Lannon stone, asbestos shingles

**Roof** Asphalt shingles

**Roof Type** Gable (multiple)

**Window Type & Materials** 4/1, 3/1, & Chicago style: wood

**Porch** Open portico with front gabled roof and decorative rafter tails

**Architectural Details** Prominent front-facing brick chimney with brick pattern detail and built-in flower box. Windows have canvas awnings

**Alterations** Lannon stone side addition which encompasses the front entry; front entry porch roof enlarged, front door has been altered to French doors of wood with metal storm doors. Addition to the rear of the house. Eaves have been boxed with synthetic siding.

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates** Schmaedeke Funeral Home opens at this site in 1932-re: "The Orland Story"

**Surveyor** PV/DE

**Date** 03/12/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14216 Union Avenue

**Map Key** L- 2

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14216 Union Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Not visible

**Walls** Brick, synthetic siding, Lannon stone

**Roof** Asphalt shingles

**Roof Type** Side- gable with front gable portico

**Window Type & Materials** 1/1, bay window with simulated divided lights; octagonal wood windows

**Porch** Portico with octagonal window in gable

**Architectural Details**

**Alterations** Siding; bay window; porch columns; one-story brick addition; two-story addition at the side and rear

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/12/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14217 Union Avenue

**Map Key** L- 3

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14217 Union Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Hipped

**Number of Stories** 1

**Materials**

**Foundation** Formed concrete block (partially parged)

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Wood 3/1 & Chicago window

**Porch**

**Architectural Details** Interior brick chimney

**Alterations** Siding; non-original door

## HISTORY

**Original Construction Date** c1930

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor**

**Date** 03/12/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14227 Union Avenue

**Map Key** L- 4

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14227 Union Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Minimal Traditional

**Number of Stories** 1

**Materials**

**Foundation** Concrete block (partially parged)

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable on Hipped roof

**Window Type & Materials** Chicago window, 1/1 wood

**Porch** Integral porch with no posts and an iron railing

**Architectural Details** Interior brick chimney

**Alterations** Siding; large rear addition

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/12/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14228 Union Avenue

**Map Key** L- 5

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14228 Union Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Minimal Traditional

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Side- gable

**Window Type & Materials** Wood, 1/1 set in pairs

**Porch**

**Architectural Details** Wood door with horizontal lights; interior brick chimney

**Alterations**

## HISTORY

**Original Construction Date** c1945

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/12/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14231 Union Avenue

**Map Key** L- 6

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14231 Union Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick, synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped with front-facing gable

**Window Type & Materials** Wood: 2/2 with horizontal muntins

**Porch** Integral porch with a front-facing low wall at the stair end

**Architectural Details** Interior brick chimney; integral garage

**Alterations**

## HISTORY

**Original Construction Date** c1960

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/12/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14236 Union Avenue

**Map Key** L- 7

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use**

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14236 Union Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoTraditional

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Brick; stone; synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable & hip

**Window Type & Materials** Synthetic: 6/6 & 4/4 with simulated divided lights

**Porch** Open portico at hexagonal entrance bay

**Architectural Details** Pair of dormer windows at garage bay

**Alterations**

## HISTORY

**Original Construction Date** 2006-re: permit records

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/12/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14306-10 Union Avenue

**Map Key** L- 8

**Common Name** Old Orland Insurance

**Historic Name** Orland Park Hotel

**Current Use** Commercial/Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Yes

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14306-10 Union Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** 19th Century Commercial / Storefront / Italianate

**Number of Stories** 2+

**Materials**

**Foundation** Brick

**Walls** Wood clapboard; synthetic

**Roof** Asphalt shingles

**Roof Type** Front gable with false facade front

**Window Type & Materials** Wood 1/1 double-hung; wood 2/2 vertical light double-hung; storefronts: fixed divided lights

**Porch**

**Architectural Details** False facade front with Italianate details; cornice has paired, carved brackets and dentils under the eave; segmental arch window hoods at front and squared window hoods at sides; cornice above first floor has carved brackets and dentils under the eave; uppermost center window opening has paired arched topped windows

**Alterations** Synthetic siding; storefronts have been altered; doors altered; transom over door covered

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14314 Union Avenue

**Map Key** L- 9

**Common Name** Union Avenue General Store

**Historic Name** Loebe Brothers

**Current Use** Commercial/Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Good

## Local Landmark

**Individual** Yes

**Old Orland Historic District** Contributing

## National Register

**Individual** No



14314 Union Ave\_2.jpg

## DESCRIPTION

### Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** 19th Century Commercial / Storefront / Italianate

**Number of Stories** 2

### Materials

**Foundation** Limestone; parged; brick at additions

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with squared false facade front; residential additions are side gable with hipped porch roofs

**Window Type & Materials** Wood fixed windows at storefronts with original bulkheads and paired wood doors and transoms; wood 1/1 double-hung windows; residential addition has Queen Anne window

**Porch** Open porch with turned wood posts and hipped roof

### Architectural Details

**Alterations** Synthetic siding; window hoods have been removed; early residential addition

## HISTORY

**Original Construction Date** 1879

**Architect/Builder**

**Associated Events, People, Dates** Constructed as a stagecoach station four miles away, the building was moved to its present site in 1880. In 1898, brothers John & Albert Loebe opened Loebe Brothers general store which closed in 1969.

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14301 West Avenue

**Map Key** M 1

**Common Name**

**Historic Name** Rectory

**Current Use** Commercial

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



1431 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style** Bungalow

**Number of Stories** 1

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Hipped

**Window Type & Materials** Wood 3/1 light, double-hung windows

**Porch** Open wood front porch with front gabled roof, square posts

**Architectural Details** Brick interior chimney

**Alterations**

## HISTORY

**Original Construction Date** 1903 per church building plaque **Architect/Builder**

**Associated Events, People, Dates** This house served as the rectory to the adjacent church

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14313-15 West Avenue

**Map Key** M 2

**Common Name** Barber Shop

**Historic Name**

**Current Use** Commercial

**Historic Use** Commercial

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Non-contributing

**National Register**

**Individual** No



14313-15 West Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** 20th Century Commercial

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Concrete block

**Roof** Built-up bituminous, clay tile coping

**Roof Type** Flat with false-front

**Window Type & Materials** Wood: fixed

**Porch**

**Architectural Details** Recessed, angled entrance at the center with concrete steps and metal railings; short false-front at the cornice

**Alterations** Wood lattice applied to cornice

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14402 West Avenue

**Map Key** M 3

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14402 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoColonial

**Number of Stories** 2 1/2

**Materials**

**Foundation** Formed concrete block, concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Synthetic: 1/1

**Porch** Partial open porch with hipped roof and turned posts and balustrades; door with etched glass oval upper panel and matching sidelights

**Architectural Details** Originally side gable or gabled ell altered with extensive additions and two-story attached garage; gabled roof dormers; exterior brick chimney.

**Alterations** Interior brick chimney covered with synthetic siding; additions/alterations in 1990 & 2007-re: permit records

## HISTORY

**Original Construction Date** c1980

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14412 West Avenue

**Map Key** M 4

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14412 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Dutch Colonial

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gambrel with gabled side porch

**Window Type & Materials** Wood: multi light casement; Vinyl: 6/1 with simulated divided lights

**Porch** Roof overhang (segmental arch) supported by wall brackets; wood paneled door with sidelights

**Architectural Details** Exterior end-wall brick chimney; 1-story side porch (screened), shutters, attached garage

**Alterations** Siding, windows

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14424 West Avenue

**Map Key** M 5

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14424 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Split Level

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Brick, wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: divided light casements, 6/6, single light window, bay

**Porch** Recessed entry with brick steps and concrete stair wall

**Architectural Details** Integral garage; secondary entrance adjacent to the garage doors

**Alterations**

## HISTORY

**Original Construction Date** c1970

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14428 West Avenue

**Map Key** M 6

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14428 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Split Level

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Brick, synthetic siding, stone

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Not visible (obscured by storm windows); 1/1

**Porch** Open partial porch with hipped roof and wood columns, wood deck, steps and railing

**Architectural Details** Integral garage

**Alterations**

## HISTORY

**Original Construction Date** c1970

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14436 West Avenue

**Map Key** M 7

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14436 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Not visible

**Walls** Brick, wood siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Window material not visible; 1/1, picture window, single light window

**Porch** Front entrance slightly recessed under the roofline

**Architectural Details** Brick bay

**Alterations**

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14515 West Avenue

**Map Key** M 8

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14515 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Colonial Revival / Cape Cod shape

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: 1/1, picture window

**Porch** Open concrete steps and wood railings, side open porch at side door

**Architectural Details** Gabled projecting entrance; metal awnings

**Alterations** Siding, steps and railing

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14516 West Avenue

**Map Key** M 9

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14516 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Wood siding, stone

**Roof** Asphalt shingle

**Roof Type** Side-gable (with front gable at entrance and dormer)

**Window Type & Materials** Wood: 2/2 (horizontal), awning, 1/1

**Porch** Concrete steps with metal awning; wood paneled door with glazing

**Architectural Details** Large interior stone chimney; integral garage

**Alterations**

## HISTORY

**Original Construction Date** 1956 per owner

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14518 West Avenue

**Map Key** M 10

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14518 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front, altered

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete block

**Walls** Synthetic siding, wood siding

**Roof** Asphalt shingles

**Roof Type** Side-gable with a front gable to the rear and at the garage

**Window Type & Materials** Wood: 2/2 (horizontal), 1/1, octagonal

**Porch** Open, partial porch with shed roof, turned posts and balusters, wood steps and deck

**Architectural Details** Interior brick chimney

**Alterations** Appears to be a Gable-Front house with a side gable addition at the front with an integral garage

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14519 West Avenue

**Map Key** M 11

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14519 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Colonial Revival

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Side-gable

**Window Type & Materials** Wood: 1/1 & casements (possibly replacements)

**Porch** Open concrete steps and metal railing; paneled front door with a top row of 3 vertical lights (probably original)

**Architectural Details** Gabled roof dormers; gabled projecting entrance

**Alterations** Siding

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14522 West Avenue

**Map Key** M 12

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14522 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Gable-Front, altered

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete, stone

**Walls** Brick, vertical wood siding

**Roof** Asphalt shingles, built-up bituminous

**Roof Type** Gable, shed, flat

**Window Type & Materials** Wood: casement, awning

**Porch** Recessed entrance under the flat roof

**Architectural Details**

**Alterations** Side and front additions that obscure most of the original building including a 1-story front addition of brick with an angled end wall and having a ribbon of 6 windows. At the side are a shed wall dormer and 1-story brick addition along the entire length of the house.

## HISTORY

**Original Construction Date** c1900, altered c1970

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14525 West Avenue

**Map Key** M 13

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14525 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Bungalow

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped with gabled front dormer

**Window Type & Materials** Wood:3/1

**Porch** Open concrete steps, wood railing; wood 6 panel front door (original)

**Architectural Details** Symmetrical facade with center entry and three windows at each side; brick interior chimney, brick exterior side chimney

**Alterations** Siding, railing

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14529 West Avenue

**Map Key** M 14

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use**

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14529 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoTraditional

**Number of Stories** 2

**Materials**

**Foundation** Concrete

**Walls** Wood siding

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Synthetic: casements with simulated divided lights, sash at second floor has triangular transom with simulated divided lights

**Porch**

**Architectural Details** Main part of the house is side gabled; at the front is a lower, 2-story projecting front gable and a projecting 1-story gable having a bay window

**Alterations**

## HISTORY

**Original Construction Date** c1990

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14550 West Avenue

**Map Key** M 15

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity**

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14550 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Hipped, altered

**Number of Stories** 2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Unknown material: 1/1, picture window, round arch window

**Porch** Open partial porch at center entrance bay with square posts, hipped roof, and paneled front door with sidelights

**Architectural Details** Symmetrical facade with a projecting full-height center bay with a gabled roof.

**Alterations** Siding, windows; remodeled 2000 re: permit records

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14557 West Avenue

**Map Key** M 16

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14557 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey

**Architectural Type/Style** Bungalow

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Cross-gable

**Window Type & Materials** Wood: 3/1; Synthetic: casements

**Porch** Open, partial porch with non-original columns and front door with an oval light and sidelights; concrete steps and stair end walls

**Architectural Details**

**Alterations** Siding, windows

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates** Constructed by William Kollman, a former Orland Park mayor from 1931 through 1941 (Source: Oral history compiled by Joyce Lahti).

**Surveyor** PV/DE

**Date** 03/20/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14558 West Avenue

**Map Key** M 17

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14558 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Craftsman

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Side- gable

**Window Type & Materials** Wood: multi-light, 4/1, (wood storm windows)

**Porch** Integral, full-width porch with shed roof, arches between porch supports, brick piers with limestone caps and wood multi-light windows

**Architectural Details** Gabled dormer, full porch, exposed rafters; interior brick chimney

**Alterations** Siding,

## HISTORY

**Original Construction Date** c1915

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14561 West Avenue

**Map Key** M 18

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14561 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey

**Architectural Type/Style** Bungalow

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick

**Roof** Asbestos shingles in diamond pattern & ridge shingles

**Roof Type** Hipped

**Window Type & Materials** Synthetic: 1/1

**Porch** Wood deck and railing at the front door constructed over concrete steps

**Architectural Details** Stone window sills; jerkinhead roof over front door; hexagonal bay at the side; slightly projecting entrance bay with centered door and 1/1 window to each side; exterior brick chimneys

**Alterations** Windows; rear addition with exposed rafter tails

## HISTORY

**Original Construction Date** c1940

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14562 West Avenue

**Map Key** M 19

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14562 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Side-gable

**Window Type & Materials** Wood: 3/1, Chicago window with 1/1 side windows, single light

**Porch** Concrete deck, steps & metal railing

**Architectural Details** Gabled bay at the front of the house

**Alterations** Siding

## HISTORY

**Original Construction Date** c1930

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14563 West Avenue

**Map Key** M 20

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14563 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable

**Number of Stories** 1

**Materials**

**Foundation** Concrete block (some parged)

**Walls** Synthetic siding and wood vertical siding

**Roof** Asphalt shingles

**Roof Type** Side-gable

**Window Type & Materials** Synthetic: sliding, casement, fixed

**Porch** Concrete steps

**Architectural Details** Exterior brick chimney with limestone details; attached garage

**Alterations** Siding

## HISTORY

**Original Construction Date** c1950

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14572 West Avenue

**Map Key** M 21

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14572 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Prairie

**Number of Stories** 2

**Materials**

**Foundation** Not visible

**Walls** Brick

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Wood: 3/1, divided lights at basement, casements with multi-divided lights

**Porch** Enclosed brick porch with hipped roof and windows on three sides, accessible only from the interior

**Architectural Details** Wide eaves, stone sills and medallion details, large exterior brick chimney with limestone trim; main entry is to the side of the front facade and recessed; limestone steps to the front door with flared metal awning above

**Alterations** Newer window boxes at the porch; rear 1-story addition, wood sided

## HISTORY

**Original Construction Date** c1900

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14575 West Avenue

**Map Key** M 22

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14575 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** NeoTraditional

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Brick, field stone, wood shingles

**Roof** Asphalt shingles

**Roof Type** Multiple gables

**Window Type & Materials** Synthetic: 4/1, 9/1, 8/8, fixed, 1/6, all with simulated divided lights

**Porch** Recessed entry with synthetic panel door, sidelights and transom

**Architectural Details** Wall surfaces are alternately covered with brick, stone or shingles, multiple projecting gables and dormers and bays; attached garage at right angle to the street

**Alterations**

## HISTORY

**Original Construction Date** c2005

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14576 West Avenue

**Map Key** M 23

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14576 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Bungalow

**Number of Stories** 1 1/2

**Materials**

**Foundation** Not visible

**Walls** Brick, vertical wood siding

**Roof** Asphalt shingle

**Roof Type** Hipped

**Window Type & Materials** Wood: 1/1, single light

**Porch** Integral porch, open with brick columns and wood beams

**Architectural Details** Hipped front dormer; brick side bay with hipped roof and French doors; interior brick chimney

**Alterations** Porch has been altered; front door non-original with large glass light in upper panel

## HISTORY

**Original Construction Date** c1910

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14606 West Avenue

**Map Key** M 24

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14606 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Horizontal and vertical wood siding

**Roof** Asphalt shingles

**Roof Type** Side-gable

**Window Type & Materials** Wood: casement, fixed, 1/1

**Porch**

**Architectural Details** Louvers below front windows, interior chimney, wood door with glazing

**Alterations**

## HISTORY

**Original Construction Date** c1970

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14614 West Avenue

**Map Key** M 25

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14614 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Side Gable

**Number of Stories** 2

**Materials**

**Foundation** Concrete block

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Side- gable

**Window Type & Materials** Non-original: 1/1

**Porch** Concrete steps, metal railings

**Architectural Details** Gabled, projecting entrance

**Alterations** Siding, windows; Second floor addition 1993 re: permit records

## HISTORY

**Original Construction Date** c1970

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14622 West Avenue

**Map Key** M 26

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Low

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14622 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Minimal Traditional, altered

**Number of Stories** 1 1/2

**Materials**

**Foundation** Concrete

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Side- gable

**Window Type & Materials** Wood: 2/2 (horizontal), picture window; Unknown: 1/1

**Porch** Projecting front gable roof over door with wood posts, concrete steps and short brick wall to one side

**Architectural Details** Large exterior end-wall chimney of brick with limestone details; gabled side porch

**Alterations** Gabled addition

## HISTORY

**Original Construction Date** c1940

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14632 West Avenue

**Map Key** M 27

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14632 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Bungalow, altered

**Number of Stories** 1 1/2

**Materials**

**Foundation** Not visible

**Walls** Brick, synthetic siding

**Roof** Asphalt shingles

**Roof Type** Cross- gable

**Window Type & Materials** Wood: 4/1, 2/1, divided light at basement; Unknown: 1/1; wood storm windows

**Porch** Partial porch enclosed, concrete steps, brick end walls with limestone caps, paneled door with sidelights and transom

**Architectural Details** Hexagonal bay at the front, brick beltcourse (two rows of banding)

**Alterations** Second floor gabled dormers at each side; synthetic siding at second floor front gable; non-original flower boxes; porch sidelights & transom are non-original

## HISTORY

**Original Construction Date** c1920

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14661 West Avenue

**Map Key** M 28

**Common Name** Jacob Hostert Log Cabin

**Historic Name**

**Current Use** Museum

**Historic Use** Residential

**Integrity** Medium

**Condition** Fair

### Local Landmark

**Individual** Eligible

**Old Orland Historic District** N/A

### National Register

**Individual** Yes - eligible



14661 West Avenue\_Hostert Log Cabin.jpg

## DESCRIPTION

### Inclusion in Previous Surveys

**Architectural Type/Style** Midland Tradition Log House

**Number of Stories** 1

### Materials

**Foundation** Rubble stone

**Walls** Log, rough hewn

**Roof** Wood shingles

**Roof Type** Gable

**Window Type & Materials** Wood: 9 divided lights, single sash

### Porch

**Architectural Details** Large rubble-stone end chimney; front door, single window at the front; low roof pitch

**Alterations** Original chinking material replaced with portland cement mix and further sealed with caulk; windows are covered with plexiglass; wood door not original

## HISTORY

**Original Construction Date** c1850

**Architect/Builder** Jacob Hostert

**Associated Events, People, Dates** Hostert was one of the first settlers in the Orland area and built this cabin on his farm; the cabin was moved and rebuilt at this location in 1980 and is operated as a museum.

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14663 West Avenue

**Map Key** M 29

**Common Name** Bernard Hostert Log Cabin

**Historic Name**

**Current Use** Museum

**Historic Use** Residential

**Integrity** Medium

**Condition** Fair

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** Yes - eligible



14663 West Avenue\_Hostert Log Cabin.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Midland Tradition Log House

**Number of Stories** 1

**Materials**

**Foundation** Rubble stone

**Walls** Logs, rough hewn and vertical wood planks under the gables

**Roof** Wood shingles

**Roof Type** Gable

**Window Type & Materials** Wood, 4 divided lights, single sash

**Porch**

**Architectural Details** Side gable with walls of rough hewn logs and vertical wood planks under the gables

**Alterations** Original chinking material replaced with portland cement mix and further sealed with caulk; windows are covered with plexiglass; wood door not original

## HISTORY

**Original Construction Date** c1850

**Architect/Builder** Bernard Hostert

**Associated Events, People, Dates** Hostert was one of the first settlers in the Orland area and built this cabin on his farm; the cabin was moved to this location in 1987 and is operated as a museum.

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14671 West Avenue

**Map Key** M 30

**Common Name** Orland Township Youth Services

**Historic Name**

**Current Use** Municipal

**Historic Use**

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14671 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** National: Hipped

**Number of Stories** 1

**Materials**

**Foundation** Concrete block

**Walls** Wood siding

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Synthetic 1/1

**Porch** Hipped entry with metal posts and concrete deck

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date** c1980

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14672 West Avenue

**Map Key** M 31

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** N/A

**National Register**

**Individual** No



14672 West Avenue.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Ranch

**Number of Stories** 1

**Materials**

**Foundation** Concrete

**Walls** Brick

**Roof** Asphalt shingles

**Roof Type** Hipped

**Window Type & Materials** Wood: 1/1, picture window

**Porch**

**Architectural Details** Wood door with raised panels and glazing

**Alterations**

## HISTORY

**Original Construction Date** c1960

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV/DE

**Date** 03/20/2008

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** Humphrey Woods

**Map Key** N- 1

**Common Name** Humphrey Woods

**Historic Name** Humphrey Woods

**Current Use** Natural wooded landscape

**Historic Use** Woods

**Integrity** High

**Condition**

**Local Landmark**

**Individual** Yes - eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



Humphrey Woods.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey; 2005 Residential Survey

**Architectural Type/Style**

**Number of Stories**

**Materials**

**Foundation**

**Walls**

**Roof**

**Roof Type**

**Window Type & Materials**

**Porch**

**Architectural Details**

**Alterations**

## HISTORY

**Original Construction Date**

**Architect/Builder**

**Associated Events, People, Dates**