



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945159.668 : YCoordinate 1811910.944 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901201485																				
6/23/2019 4:08 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.00	2945220.66937324 1811887.54993639	Passenger	North	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901341382																				
9/27/2019 6:56 PM	Rain	Wet	0	0	1	0	Turning	Darkness, Lighted Road	0.00	2945220.66937324 1811887.54993639	Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	2
											Passenger	North	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901365256																				
10/14/2019 8:05 PM	Clear	Dry	0	0	1	0	Front to Rear	Darkness	0.00	2945220.66937324 1811887.54993639	Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901084895																				
3/16/2019 3:45 PM	Clear	Dry	0	0	1	0	Front to Rear	Daylight	38.00	2945162.94604124 1811884.84363828	Pickup	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901404226																				
11/11/2019 7:26 AM	Snow	Snow or Slush	0	0	1	0	Fixed Object	Daylight	38.00	2945165.97830877 1811886.04528691	Passenger	East	Skidding/Co ntrol Loss	Ran Off Roadway	Off Pavement - Right	Tree or Shrub	Off Pavement - Right	(UNK)	(UNK)	1



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945159.668 : YCoordinate 1811910.944 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901163406																				
5/28/2019 10:44 AM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	38.02	2945167.03028476 1811809.10745193	SUV	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901320643																				
9/11/2019 9:50 AM	Clear	Dry	0	0	2	0	Front to Rear	Daylight	7.67	2945168.9857992 1811776.72395797	Van/Mini-Van	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											Pickup	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901117036																				
4/19/2019 9:45 AM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	7.68	2945222.67453813 1811814.66904864	Pickup	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901443979																				
12/13/2019 6:18 AM	Clear	Dry	0	0	0	0	Turning	Dawn	7.68	2945195.32892114 1811813.91670866	Pickup	Southeast	Turning Right	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	South	Straight Ahead	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2
201901210829																				
6/19/2019 9:48 PM	Rain	Wet	0	0	0	0	Front to Rear	Darkness	7.69	2945205.20678291 1811862.1820661	Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945159.668 : YCoordinate 1811910.944 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901340683																				
9/26/2019 4:56 PM	Clear	Dry	0	1	0	0	Front to Rear	Daylight	7.69	2945163.28045518 1811878.64243205	Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901012363																				
1/4/2019 5:20 PM	Clear	Dry	0	0	0	0	Turning	Darkness, Lighted Road	7.70	2945161.45682313 1811909.6269259	Passenger	Southeast	Turning Right	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901014715																				
1/7/2019 6:10 PM	Clear	Wet	0	0	0	0	Turning	Darkness, Lighted Road	7.70	2945161.53323243 1811909.6321912	SUV	West	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901041084																				
2/1/2019 4:24 PM	Clear	Wet	0	0	0	0	Front to Rear	Daylight	7.70	2945161.70630335 1811909.64411756	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901048458																				
2/2/2019 7:23 PM	Clear	Wet	0	0	0	0	Turning	Darkness	7.70	2945161.3425139 1811909.61904894	SUV	West	Turning Left	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	South	Straight Ahead	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945159.668 : YCoordinate 1811910.944 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901060655																				
2/17/2019 5:13 PM	Snow	Snow or Slush	0	0	0	0	Turning	Darkness, Lighted Road	7.70	2945161.24964674 1811909.61264953	Passenger	West	Turning Left	Motor Vehicle In Traffic	Intersection	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	1
											Van/Mini-Van	South	Straight Ahead	Motor Vehicle In Traffic	Intersection	Ran Off Roadway	Off Pavement - Right	Other Fixed Object	Off Pavement - Right	2
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901069581																				
2/27/2019 11:01 AM	Cloudy/Overcast	Dry	0	0	0	0	Front to Rear	Daylight	7.70	2945157.32514696 1811909.34221527	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901112463																				
4/14/2019 1:23 PM	Snow	Snow or Slush	0	0	0	0	Turning	Daylight	7.70	2945161.41709134 1811909.62418801	SUV	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	Northeast	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901152701																				
5/17/2019 3:40 PM	Clear	Dry	1	0	0	0	Turning	Daylight	7.70	2945161.14822522 1811909.60566065	Passenger	Northwest	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	Other Object	Off Pavement - Left	(UNK)	(UNK)	1
											Pickup	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901195155																				
6/18/2019 6:00 PM	Clear	Dry	0	1	1	0	Turning	Daylight	7.70	2945193.32384088 1811886.79759577	Passenger	North	Turning Left	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945159.668 : YCoordinate 1811910.944 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901272823																				
8/12/2019 3:40 PM	Rain	Wet	0	0	0	0	Front to Rear	Daylight	7.70	2945161.34790281 1811909.61942028	Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901304950																				
9/3/2019 10:41 AM	Cloudy/Overcast	Wet	0	0	2	0	Front to Rear	Daylight	7.70	2945203.00551176 1811912.49008628	SUV	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	North	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											Passenger	North	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901371261																				
10/19/2019 7:01 PM	Clear	Dry	0	0	0	0	Fixed Object	Dusk	7.70	2945161.12454966 1811909.60402919	SUV	South	Straight Ahead	Traffic Signal	Off Pavement - Right	(UNK)	(UNK)	(UNK)	(UNK)	1
201901449487																				
12/19/2019 3:37 PM	Clear	Dry	0	0	1	0	Turning	Daylight	7.70	2945160.56322666 1811909.56534885	Passenger	Northwest	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	Other Fixed Object	Off Pavement - Right	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945159.668 : YCoordinate 1811910.944 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
<u>24</u>	<u>0</u>	<u>1</u>	<u>2</u>	<u>7</u>	<u>14</u>	<u>0</u>	<u>13</u>	<u>1</u>	<u>2</u>	<u>10</u>

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Fixed Object	2	8.3%	Monday	4	16.7%	06 AM	1	4.2%	Passenger	28	54.9%
Front to Rear	11	45.8%	Tuesday	3	12.5%	07 AM	1	4.2%	Pickup	8	15.7%
Turning	11	45.8%	Wednesday	3	12.5%	09 AM	2	8.3%	SUV	13	25.5%
TOTAL:	24		Thursday	2	8.3%	10 AM	2	8.3%	Van/Mini-Van	2	3.9%
			Friday	6	25.0%	11 AM	1	4.2%	TOTAL:	51	
			Saturday	3	12.5%	1 PM	1	4.2%			
			Sunday	3	12.5%	3 PM	4	16.7%			
			TOTAL:	24		4 PM	3	12.5%			
					5 PM	2	8.3%				
					6 PM	3	12.5%				
					7 PM	2	8.3%				
					8 PM	1	4.2%				
					9 PM	1	4.2%				
					TOTAL:	24					

Weather Cond	Total	%	Light Cond	Total	%	Road Surface	Total	%	DIRP	Total	%
Clear	16	66.7%	Darkness	3	12.5%	Dry	14	58.3%	East	6	11.8%
Cloudy/Overcast	2	8.3%	Darkness, Lighted Road	4	16.7%	Snow or Slush	3	12.5%	North	10	19.6%
Rain	3	12.5%	Dawn	1	4.2%				Northeast	1	2.0%

**Coordinate Collision Diagram Report**

1/1/2019 to 12/31/2019

For XCoordinate 2945159.668 : YCoordinate 1811910.944 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

<i>Weather Cond</i>	<i>Total</i>	<i>%</i>	<i>Light Cond</i>	<i>Total</i>	<i>%</i>	<i>Road Surface</i>	<i>Total</i>	<i>%</i>	<i>DIRP</i>	<i>Total</i>	<i>%</i>
Snow	3	12.5%	Daylight	15	62.5%	Wet	7	29.2%	Northwest	2	3.9%
TOTAL:	24		Dusk	1	4.2%	TOTAL:	24		South	26	51.0%
			TOTAL:	24					Southeast	2	3.9%
									West	4	7.8%
									TOTAL:	51	



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945159.668 : YCoordinate 1811910.944 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.